

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0928/2021/JT  
DATE : 15-Nov-21  
WIP : 53471

*Xiao Chen.*

*\$12908.72.*

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/11/2021

**AIG ASIA PACIFIC INSURANCE PTE LTD**  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
Attn: Motor Claims Dept  
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR NAVINDER SINGH  
ADDRESS : 8 BOON LAY DRIVE  
#05-18  
SINGAPORE 649928  
TELEPHONE : HP +65 96510144  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 1900171694-01  
VEHICLE NO : **SMP 5965 U**  
MODEL CODE : AUDI A5 2.0 TFSI  
MODEL YEAR : 30/9/2019  
ENGINE NO : CVK 086254  
CHASSIS NO : WAUZZZF55KA068566  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 12-Nov-21  
PLACE OF ACCIDENT : OUTSIDE 22,24,26 SOUTH  
BOUNA VISTA ROAD

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 5965 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	25? ✓
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,200.00	1000 ✓
4	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND LHS FRONT FENDER.	\$ 3,500.00	1650 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 7,772.00</b>	

APPROVED BY: \_\_\_\_\_  
 DATE: \_\_\_\_\_  
 APPROVED BY: \_\_\_\_\_  
 DATE: \_\_\_\_\_

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL 6366 2323 FAX 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5965 U

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Rehd</i>	1	\$ 2,251.00	1800.80	
2	FRONT BUMPER FIXING PARTS <i>2</i>	1	\$ 407.00		
3	FRONT BUMPER SECURING STRIP <i>2</i>	2	\$ 71.00		
4	FRONT BUMPER GRILLE - CENTER <i>Non</i>	1	\$ 196.00		
5	FRONT BUMPER CLOSING ELEMENT LOWER - CENTER <i>Non</i>	1	\$ 228.00		
6	FRONT BUMPER AIR GUIDE - LH <i>Non</i>	1	\$ 63.00		
7	PADIATOR GRILLE <i>Non</i>	1	\$ 2,326.00		
8	FRONT PARKING AID SENSOR SUPPORT - LH / RH <i>2</i>	2	\$ 102.00		
9	FRONT RADIATOR GRILLE UPPER BRACKET <i>2</i>	1	\$ 189.00		
10	FRONT AIR GUIDE - LH <i>2</i>	1	\$ 474.00		
11	FRONT BUMPER FOAM FILLER PIECE <i>2</i>	1	\$ 124.00		
12	FRONT BUMPER REINFORMENT BEAM <i>2</i>	1	\$ 845.00		
13	FRONT BUMPER GUIDE SECTION - LH <i>cracked</i>	1	\$ 36.00	28.72 ✓	
14	FRONT BUMPER TOP COVER <i>Non</i>	1	\$ 127.00		
15	"CAUTION" STICKER <i>2</i>	1	\$ 14.00		
16	AIRCON STICKER <i>2</i>	1	\$ 8.00		
17	FRONT BUMPER LOCK CARRIER <i>2</i>	1	\$ 137.00		
18	FRONT BUMPER SUPPORT - LH / RH <i>2</i>	2	\$ 58.00		
19	HORN - LH <i>2</i>	1	\$ 126.00		
20	HORN BRACKET - LH <i>2</i>	1	\$ 29.00		
<b>SUB TOTAL SPARE PARTS</b>			<b>\$ 7,811.00</b>		

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL 6366 2323 FAX 6841 1183  
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5965 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	FRONT PARKING AID SENSOR	1	TBC	x
22	FRONT PARKING AID SENSOR SEAL RING	4	\$ 14.00	x
23	FRONT FENDER - LH <i>Dented</i>	1	\$ 1,060.00	✓ 848
24	FRONT FENDER ATTACHEMENT PARTS <i>new</i>	1	\$ 53.00	+
25	FRONT FENDER CLOSING ELEMENT - LH <i>new</i> dmg	1	\$ 74.00	✓ 59.04 ✓
26	FRONT FENDER BRACKET CENTER - LH <i>new</i> dmg	1	\$ 35.00	✓ 27.92 ✓
27	POP RIVET <i>Not nec</i>	5	\$ 17.00	✗
28	FRONT FENDER BRACE - LH <i>Bent</i>	1	\$ 118.00	✓ 94.40 ✓
29	FRONT FENDER BRACKET - LH <i>Not Nec</i>	1	\$ 49.00	✗
30	FRONT FENDER TRIM - LH <i>new</i>	1	\$ 164.00	130.80
31	FRONT WHEEL HOUSING LINER - LH <i>new</i>	1	\$ 275.00	+
32	FRONT WHEEL HOUSING LINER ATTACHEMENT PARTS <i>new</i>	1	\$ 169.00	+
33	FRONT WHEEL SPOILER - LH <i>new</i>	1	\$ 73.00	+
34	FRONT SPOILER - LH <i>new</i>	1	\$ 35.00	+
35	FRONT FENDER FLEDGE COVER - LONG <i>Not nec</i>	1	\$ 36.00	✗
36	FRONT FENDER FLEDGE COVER - SHORT <i>Deformed</i>	1	\$ 16.00	✓ 12.24 ✓
37	BONNET <i>new</i>	1	\$ 3,312.00	x
38	CAP NUT <i>Not nec</i>	6	\$ 24.00	+
39	BONNET ATTACHEMENT PARTS <i>new</i>	1	\$ 123.00	x
40	BONNET HINGE - LH / RH <i>Not nec</i>	2	\$ 838.00	x
<b>SUB TOTAL SPARE PARTS</b>		:	<b>\$ 6,485.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL 6366 2323 FAX 6841 1183  
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5965 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>not</i>	3	\$ 84.00	+
42	BONNET STRIKER <i>not</i>	1	\$ 50.00	+
43	BONNET LOCK <i>not</i>	1	\$ 214.00	+
44	HEADLIGHT - LH <i>cut</i>	1	\$ 7,902.00	✓ 6321.60
45	HEADLIGHT CONTROL UNIT <i>not</i>	1	\$ 751.00	+
46	HEADLIGHT POWER MODULE <i>not</i>	1	\$ 758.00	+
47	HEADLIGHT HEAT SINK - LH <i>not</i>	1	\$ 1,153.00	+
48	HEADLIGHT SPACER <i>not</i>	3	\$ 122.00	+
49	LIFT CYLINDER - LH <i>not</i>	1	\$ 198.00	+
50	LIFT CYCLINER HOSE <i>not</i>	1	\$ 86.00	+
51	FRONT NO PLATE <i>not</i>	S/N	\$ 60.00	+
52	SUNDRIES <i>nec</i>		\$ 350.00	✓ 13.20
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 26,024.00</b>	
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 7,772.00</b>	
<b>GRAND TOTAL</b>		:	<b>\$ 33,796.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL 6366 2323 FAX 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adnan King  
SURVEYED DATE : 16/11/21  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS : Not Authorised, 04 Days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: