

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ABOUT CHARGES FOR ACCIDENT REPAIRS

ESTIMATE : NATURE OF ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : RA/QD/0923/2021/JT
DATE : 11-Nov-21
WIP : 53212

VEHICLE NOT IN WORKSHOP, KINDLY ARRANGE FOR SURVEY ON 16/11/21

AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 Attn: Motor Claims Dept
 Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LEE HENG THYE
ADDRESS : 26 CACTUS CRESCENT
 SINGAPORE 809728
TELEPHONE : HP +65 90077819
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100459496-05
VEHICLE NO : SGK 93 R
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI
MODEL YEAR : 31/3/2016
ENGINE NO : CVN 004995
CHASSIS NO : WAUZZZF40GA039359
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Nov-21
PLACE OF ACCIDENT : YIO CHU KANG SLIP ROAD
 TOWARDS ANG MO KIO AVENUE 6

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGK 93 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X.
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	250 ✓
3	TO RENEW AND REINSTALL AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. TO RENEW ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	S/N \$ 1,400.00	X.
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGAINZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,200.00	1000 ✓
5	TO RESPRAY FRONT BUMPER, BONNET AND HINGES.	\$ 2,000.00	1100 ✓
6	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	192 ✓
TOTAL LABOUR CHARGES		: \$ 8,694.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGK 93 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Rehnd</i>	1	\$ 2,111.00 ✓	1688.8
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	TBC +	
3	FRONT BUMPER SECURING STRIPS ?	2	\$ 71.00 X	
4	FRONT BUMPER GRILLE - CENTER <i>cracked</i>	1	\$ 196.00 ✓	156.4
5	FRONT BUMPER CLOSING ELEMENT LOWER - CENTER <i>new</i>	1	\$ 210.00 +	
6	FRONT BUMPER AIR GUIDE - LH / RH <i>new</i>	2	\$ 126.00 +	
7	RADIATOR GRILLE <i>cracked</i>	1	\$ 1,152.00 ✓	921.6
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2	\$ 270.00 +	
9	FRONT BUMPER FOAM FILLER PIECE ? <i>cracked</i>	1	\$ 124.00 ✓	99.2
10	FRONT BUMPER REINFORCEMENT BEAM ? <i>dented</i>	1	\$ 845.00 ✓	675.6
11	FRONT BUMPER TOP COVER <i>cracked</i>	1	\$ 127.00 ✓	101.6
12	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$ 72.00 +	
13	"CAUTION" STICKER ? <i>new</i>	1	\$ 14.00 ✓	10.88
14	AIR COND STICKER	1	\$ 8.00 ✓	5.68
15	FRONT BUMPER BRACKET - LH ?	1	\$ 228.00 ?	
16	LOCK CARRIER TOP BRACKET ? <i>cracked</i>	1	\$ 137.00 ✓	109.6
17	LOCK CARRIER SUPPORT - LH / RH ? <i>nec</i>	2	\$ 58.00 ?	44.96
18	HORN HIGH TONE - LH ? <i>new</i>	1	\$ 126.00 +	
19	HORN BRACKET - LH	1	\$ 29.00 +	
20	BONNET <i>Dented</i>	1	\$ 3,246.00 ✓	2596.8
SUB TOTAL SPARE PARTS		:	\$ 9,150.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGK 93 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET ATTACHMENT PARTS <i>Not m</i>	1	\$ 412.00	x
22	BONNET HINGE - LH / RH <i>Not m</i>	2	\$ 610.00	x
23	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>Not m</i>	3	✓ 84.00	✓ 65.68
24	BONNET BOWDEN CABLE <i>? Not m</i>	1	\$ 58.00	x
25	BONNET RELEASE LEVER <i>? Not m</i>	1	\$ 14.00	x
26	BONNET BOWDEN CABLE INNER - CENTER <i>? Not m</i>	1	\$ 58.00	x
27	BONNET BOWDEN CABLE INNER COVER <i>? Not m</i>	1	\$ 10.00	x
28	BONNET STRIKER - LH <i>? Not m</i>	1	\$ 50.00	x
29	BONNET LID LOCK <i>? Not m</i>	1	\$ 214.00	x
30	LED HEADLIGHT - LH <i>cracked</i>	1	✓ 7,693.00	✓ 6154.4
31	LIFT CYLINDER - LH <i>Not m</i> damaged	1	✓ 210.00	x 167.6
32	LIFT CYLINDER CORRUGATED PIPE <i>Not m</i>	1	\$ 93.00	x
33	LOCK CARRIER <i>Not m</i>	1	\$ 1,016.00	x
34	RADIATOR SUPPORT - LH <i>to ?</i> nn	1	\$ 38.00	?
35	OUTSIDE TEMPERATURE SENSOR HOLDER <i>? nn</i>	1	\$ 19.00	?
36	RADIATOR COOLANT <i>Not m</i>	6	\$ 267.00	x
37	RADIATOR AIR GUIDE OUTER - LH / RH <i>? NN</i>	2	\$ 56.00	?
38	RADIATOR AIR GUIDE INNER - LH / RH <i>? NN</i>	2	\$ 24.00	?
39	RADIATOR AIR GUIDE - UPPER <i>? NN</i>	1	\$ 16.00	?
40	RADIATOR AIR GUIDE - LOWER <i>? nn</i>	1	\$ 22.00	?
SUB TOTAL SPARE PARTS		:	\$ 10,964.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGK 93 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
42	HEADLIGHT ELECTRONIC POWER MODULE <i>Free</i>	1	\$ 761.00	+
43	HEADLIGHT CONTROL UNIT	1	\$ 751.00	+
44	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	✓
45	SUNDRIES <i>nec</i>	1	✓ \$ 300.00	? 3.20
TOTAL SPARE PARTS		:	\$ 21,986.00	
TOTAL LABOUR CHARGES		:	\$ 8,694.00	
GRAND TOTAL		:	\$ 30,680.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Not Authorised.

Adrian Lij

16/11/21. 05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: