

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SMP1626A
 at Workshop m/s: hug notes
 of _____
 Insured: SML 4045C
 Policy No. _____
 Claims No. DM214001707/17
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SMP1626A Yr Regn: 01/10/19
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA
 Make: mit outlander c.c. 1998
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 46445 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: GF7W 0601714
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/55 R18
 R: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: \$96k.
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 1.3.1 % 3 Val.: Yes or No
397i
 CA / REV / REP. / 24 HRS
 Vehicle: IN / OUT
 Date: _____ Person Contacted: LIA 43853

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
 Front _____ Rear _____
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 13/11/21 D.O.I. 17/11/21
 Survey held at _____
 Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or
Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Rep 11k</u>

13/01/22 @ 11.47am revised to Jaime Tay by email.
18/1/22 informed David P/P \$3294.30 (cred \$3136.20, 49%)

Date/Time, File Pass to? : Preli. Report
 : Final Report
 Date/Time, File Return to?

Days Of Repair: 4
 Resurvey No. of Trip: 2

Survey Fee:	
Transportation:	
TOTAL	

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Report Format : TP
 Lump Sum / I.B.I. (\$) 3294.30)

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3041/11/21 Your Ref: _____

MR MARTIN CHIANG TEE YANG
BLK 217C, #07-220,
Sumang Walk, S (823217)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

is subject to final approval from Insurance Company

Date: 15th NOV 2021

Acknowledged by Repairer

Signature: _____

Date: _____

nett item

Estimate cost of repair to MITSUBISHI OUTLANDER 2.0 (A) SUV - SMP 1626 A

1 pc tail gate door 'OUTLANDER' emblems	<i>nee</i>	\$ 86.00	/
1 pc tail gate door 'logo' emblems	<i>nee</i>	41.00	X
1 pc tail gate door 'MIVEC' emblems	<i>nee</i>	52.00	/
1 pc tail gate door 'C&C' emblems	<i>nee</i>	48.00	/
16 pcs tail gate door inner trim board clips	<i>nee</i>	96.00	X
1 pc rear bumper	<i>D.S</i>	1,068.00	/
10 pcs rear bumper clips	<i>nee</i>	50.00	/
2 pcs rear bumper o/s & n/s stay bracket	<i>su</i>	142.00	X
2 pcs rear bumper o/s & n/s side retainer	<i>su</i>	46.00	X
1 set rear bumper reverse sensor	<i>shorted</i>	280.00	200 s/n
2 pcs rear bumper o/s & n/s reflector	<i>su</i>	180.00	X
1 pc rear bumper lower garnish	<i>nee</i>	380.00	/
10 pcs rear bumper lower garnish clips	<i>nee</i>	45.00	/
1 pc rear end panel	<i>nee</i>	354.00	X
1 pc rear end panel top garnish	<i>nee</i>	143.00	X
6 pcs rear end panel top garnish clips	<i>nee</i>	36.00	X
1 pc tail gate door key less sensor	<i>one</i>	98.00	/
		\$ 3,145.00	
	Less 1.0%	\$ 314.50	
		\$ 2,830.50	
1 pc rear bumper lower garnish black sticker	<i>nee</i>	280.00	S.N
To wiring check up for affected wiring system.		50.00	20
To remove & refix tail gate door inner trim board & necessary parts, to enable repair tail gate door.		180.00	X
To remove & refix carpet, floor mat, garnish, floor board cover, spare tyre, tool set & necessary parts.		150.00	80
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out tail gate door, rear end panel & necessary parts, to weld, renew & align above parts.		1,350.00	600
To putty & respray painting on all affected accident parts.		1,500.00	600
To respray Tuff-Kote on all affected accident parts.		90.00	X
		\$ 6,430.50	

Dollars : Six Thousand One Hundred And Sixteen Only.

HUP MOTOR TRADING & SERVICE

not allowed
nee
17/11/21
to high to be done parting

RP \$ 3294.30

4 days.

P-1827
107
P-164430
S.N-350
L-1300
3294.30