

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : Auto & General Insurance
(Singapore) Pte Ltd
190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore 239924

Claim Details
Case Ref. No. : TP/112021/5082
Date : 17-11-2021
Accident Date : 16-11-2021

Vehicle Details

Make & Model : Honda FIT 1.3 BASIC SENSING
Chassis No : GR11033416
Registration No : SNA8145S

Third Party Vehicle Details

Registration No : SJW7931C

S/N	Description	Qty	Amount (\$)
1	REAR TAILGATE / <i>Bue</i> <i>MC</i>	1.00	\$1,035.60
2	REAR TAILGATE "FIT" EMBLEM / <i>MC</i>	1.00	\$40.80
3	REAR BUMPER / <i>re</i>	1.00	\$508.30
4	REAR BUMPER LH REFLECTOR <i>X</i> <i>re</i>	1.00	\$60.30
5	REAR BUMPER LH SIDE RETAINER / <i>re</i>	1.00	\$25.10
6	REAR BUMPER CLIPS @ \$4.20 / <i>re</i>	10.00	\$42.00

\$1,712.10

Discount: -20%

(\$342.42)

\$1,369.68

7	REAR BUMPER PARKING SENSOR / <i>DM</i>	1.00	\$280.00	<i>200</i>
8	REAR WINDSCREEN GUM / <i>re</i>	1.00	\$60.00	<i>40</i>
9	TO REMOVE AND REFIX REAR WINDSCREEN	1.00	\$150.00	<i>120</i>
10	TO REPAIR DAMAGES	1.00	\$480.00	<i>300</i>
11	TO SPRAY PAINTING	1.00	\$580.00	<i>400</i>

Subtotal w/o GST:

\$2,919.68

*3 Days -
P/P
before paint jobs
Gmo Qs of
17/11/21*

Issued by Raymond Teo

This is a computer-generated document. No signature is required.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: