

Ms China Taiping Insurance (Singapore) Pte Ltd
Date 16/11/2021
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLG2890E
CHASSIS NO : GP71040457
MAKE / MODEL : Honda Shuttle 1.5 Hybrid
DATE OF ACCIDENT: 06/11/2021
YOUR INSURED VEHICLE NUMBER: SCY27G
MILEAGE : 144352 Km

Steve (LKK)
18/11/21, 10am

WHL PL
L/S
M AL sy
3 dys

	PARTS DESCRIPTION	QTY	UNIT PRICE	LIST PRICE
1	F/R door / DO	1PC	\$ 1,575.00	\$ 1,575.00 1250 ✓
2	F/R door lock assy X nn	1PC	\$ 550.00	\$ 550.00
3	F/R door mirror assy / cut ? - BT	1PC	\$ 850.00	\$ 850.00 695 ✓
4	F/R door window regulator	1PC	\$ 480.00	\$ 480.00
5	F/R door window motor assy X nn	1PC	\$ 680.00	\$ 680.00
6	RH side skirt X R	1PC	\$ 750.00	\$ 750.00
			Total	\$ 4,885.00
			Less 20%	\$ 977.00
				\$ 3,908.00

2425
-10%
1940 -

SPECIAL NETT

1	Front Bumper clips - PPC	1 SET	\$ 80.00 30 -
Special Nett Total S\$:			\$ 80.00

LABOUR CHARGES

1	To labour charge for removing F/R side mirror and front door(RH) to facilitate repairs and replacement of damaged parts. And to panel beat and to straighten RH side skirt	\$ 700.00 350
2	To respray front RH door and RH side skirt	\$ 600.00 440
3	Transfer door mechanism to facilitate repairs and replacement of parts	\$ 120.00 50
4	To configure and reset door keyless security system back to factory specifications	\$ 200.00 30

870 -

=2840

LABOUR TOTAL S\$:	\$ 1,620.00
TOTAL S\$:	\$ 5,608.00
7% GST	\$ 392.56
GRAND TOTAL S\$:	\$ 6,000.56

L/S-2272
=2250

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be removed and