



MK Vehicle Engineering Pte Ltd

48 Toh Guan Road East #04-125 Enterprise Hub, Singapore 608586

Tel: 6763 6363 / 6760 7877 (accts)

Co. Regn no. & GST Regn no.: 201623663G

TAX INVOICE

Name **FWD SINGAPORE PTE LTD**
Address **6 TEMASEK BOULEVARD #18-01**
SUNTEC TOWER FOUR SINGAPORE 038986
Owner: **LI FANG**

Invoice Date **31/03/2020**
Invoice No. **INV20030170**
Ref **SBW8283C**

Vehicle no. **SKT3214U**
Model **VOLKSWAGEN JETTA GP 1.4**

Description	Qty	Discount	Amount (\$\$)
<u>ITEM</u>			
REAR BUMPER Deformed	1PC		1,650.00 1212
REAR BUMPER SPONGE XSVC	1PC		225.00 X
REAR BUMPER SPOILER deformed	1PC		855.00 540
REAR BUMPER REINFORCEMENT XSVC	1PC		795.00 X
REAR BUMPER CENTRE RETAINER XSVC	1PC		105.00 X
REAR BUMPER RETAINER XSVC	2PC		240.00 X
REAR BUMPER REFLECTOR XSVC	2PC	1752	240.00 X
REAR END PANEL XSVC	1PC	10%	891.60 X
REAR END TOP TRIM XSVC	1PC	1576.80	561.85 X
REAR END TOP TRIM CLIPS XSVC	4PC		77.40 X
LESS DISCOUNT	10%		(564.08)
			5,076.77
<u>SPECIAL NETT ITEM</u>			
REAR NUMBER PLATE xnn	1PC		65.00 X
REAR NUMBER PLATE CASING xnn	1PC		38.00 X
REVERSE CAMERA xnn	1SET		680.00 X
REAR BUMPER NUMBER PARKING SENSOR XSVC	1SET		250.00 X
REAR BUMPER PARKING SENSOR WIRE XSVC	1PC		180.00 X
			1,213.00 0
<u>LABOUR CHARGE</u>			
1 TO CHECK WIRING			150.00 xnn
2 TO TUFF COAT AFFECTED AREA			150.00 xnn
3 TO REMOVE & REFIX INTERIOR UPHOLSTERY			150.00 xnn
4 TO REMOVE & REPLACE REVESE SENSOR & CAMERA			250.00 60
4 TO RESPRAY AFFECTED AREA			1,600.00 200
5 TO RENEW DAMAGED PARTS, STRAIGHTEN, REPAIR & ALIGNED ALL PARTS			1,400.00 200
			3,700.00
LUMP SUM REPAIR DISCOUNT			(1,489.77) 460
TOTAL REPAIR		1576.80 460.00	8,500.00
		2036.80	

P/P-\$2,036.80/3 DAYS