

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 3214U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	1,650.00	1,212.00
1	REAR BUMPER SPONGE	SERVICEABLE	225.00	-
1	REAR BUMPER SPOILER	DEFORMED	855.00	540.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	795.00	-
1	REAR BUMPER CENTRE RETAINER	SERVICEABLE	105.00	-
2	REAR BUMPER RETAINER	SERVICEABLE	240.00	-
2	REAR BUMPER REFLECTOR	SERVICEABLE	240.00	-
1	REAR END PANEL	SERVICEABLE	891.60	-
1	REAR END TOP TRIM	SERVICEABLE	561.85	-
4	REAR END TOP TRIM CLIPS	SERVICEABLE	77.40	-
	LESS 10% DISCOUNT		-564.09	-175.20
			5,076.76	1,576.80
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	65.00	-
1	REAR NUMBER PLATE CASING (SN)	NOT NECESSARY	38.00	-
1	SET REVERSE CAMERA (SN)	NOT NECESSARY	680.00	-
1	SET REAR BUMPER NUMBER PARKING SENSOR (SN)	SERVICEABLE	250.00	-
1	REAR BUMPER PARKING SENSOR WIRE (SN)	SERVICEABLE	180.00	-
			1,213.00	-
	<u>LABOUR</u>			
	TO CHECK WIRING.	NOT NECESSARY	150.00	-
	TO TUFF COAT AFFECTED AREA.	NOT NECESSARY	150.00	-
	TO REMOVE & REFIX INTERIOR UPHOLSTERY.	NOT NECESSARY	150.00	-
	TO RESPRAY AFFECTED AREA.		1,600.00	200.00
	TO RENEW DAMAGED PARTS, STRAIGHTEN, REPAIR & ALIGNED ALL PARTS.		1,400.00	200.00
	TO REMOVE & REPLACE REVERSE SENSOR & CAMERA.		250.00	60.00
			3,700.00	460.00
	GRAND TOTAL		9,989.76	2,036.80

Report Ref No. CS/FWD20004314/R1tf3e2-1



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 2,036.80

Report Ref No. CS/FWD20004314/R1tf3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

P

ANG BRYAN TANI

Automotive Assessor / Investigator