

Shiau Chan (LKKAUTO)

From: Simon Ho (LKKAUTO)
Sent: Friday, 25 February 2022 5:21 PM
To: Shiau Chan (LKKAUTO)
Subject: Re: CTI-TP SKE 8785J SURVEYED BY STEVE (OUR REF: CS/CTI21011728/Eqy3)

Dear Shiau Chan,

AUDIT CHECK DONE FOR SKE8785J, FOUND HEADREST NOT NECESSARY TO REPLACE, ONLY NEED TO REPLACE REPAIR KITS.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Friday, 25 February 2022 3:35 pm
To: Simon Ho (LKKAUTO) <SimonHo@lkkauto.com>
Subject: CTI-TP SKE 8785J SURVEYED BY STEVE (OUR REF: CS/CTI21011728/Eqy3)

Dear Simon,

For your re-audit.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)