

08/11/13) wef
ASS. REC. BY: Marcus

REF:

CC4/ASMA2011732/UPa3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJA 475A

at Workshop m/s boom

of _____

Insured: SHA4378J

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: \$24k.

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 5

days

Res.: Yes or No

Lum Sum: 20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

943

Vehicle: IN / OUT

Date: _____

Person Contacted: Rep. 1

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

) S + RS \$

) Photos

) Others

)

Report Format :

Lump Sum / I.B.I.: (\$

TOTAL



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

Lim Hsiao Tony

22 November 2021

Mr Arnold
Nah
17/11/21

REG NO.: SJU 4755 A
MAKE/MODEL: HONDA STREAM

5 days 1/58 4000

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
LIST ITEMS		
1	Rear windscreen moulding <i>all</i>	66.80
1	Rear tailgate <i>20/Bent</i>	987.20
2	Rear tailgate dampers <i>11</i>	297.00 X
1	Rear tailgate outer garnish <i>11</i>	189.00 X
1	Rear tailgate inner lock <i>Daged</i>	145.80
1	Rear tailgate inner trim board <i>11</i>	303.20 X
1	Rear tailgate logo <i>11</i>	489.50 X
1	Rear tailgate weatherstrip <i>11</i>	45.00 X
1	Rear tailgate "STREAM" emblem <i>11</i>	189.60 X
1	Rear wiper arm <i>11</i>	68.50
1	Rear wiper motor <i>11</i>	89.50 X
2	Rear taillamps <i>M5 cra</i>	390.80
1	Rear end panel <i>20/Bent</i>	440.60
1	Rear end panel inner garnish <i>11</i>	184.20
1	Rear bumper <i>D.S</i>	654.00
2	Rear bumper lower brackets <i>M5 Bent</i>	25.00
1	Rear bumper beam <i>11</i>	117.00
2	Rear bumper side retainers <i>all</i>	25.50 x 2 = 51.00
1	Rear bumper tow hook cover <i>11</i>	22.00
1	Rear floor board <i>11</i>	42.50
1	Rear exhaust silencer <i>11</i>	286.00 X
2	Rear exhaust mountings <i>11</i>	689.50 X
1	Rear fender - LH <i>11</i>	57.00 X
1	Rear fender quarter glass moulding <i>11</i>	981.60 X
1		182.60 X
		9,357.00
	Less 20%	1,871.40
		7,485.60

SPECIAL NETT ITEMS

1	Rear windscreen sealant <i>all</i>	\$ 80.00
1	Rear end panel sealant <i>all</i>	\$ 850.00
1	Rear bumper clip (1 set) <i>all</i>	\$ 60.00
1	Rear reverse sensor (1 set) <i>shorted</i>	\$ 350.00
1	Rear reverse camera <i>11</i>	\$ 480.00
1	Rear exhaust chrome tail pipe <i>11</i>	\$ 85.00
1	Rear fender quarter glass sealant <i>11</i>	\$ 80.00
		\$ 1,985.00

S/N	LABOUR CHARGES		
1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00 ³⁰
2	To remove and refit inner garnishes.	\$	150.00 ⁸⁰
3	To remove and refit rear reverse sensor and camera.	\$	150.00 ⁵⁰
4	To transfer rear tailgate mechanism and wiring assembly.	\$	120.00 ⁶⁰
5	To remove and refit rear windscreen glass.	\$	180.00 ¹²⁰
6	To remove and refit quarter glass to assist repair.	\$	120.00 ¹¹
7	To remove, refit and replace exhaust silencer and mountings.	\$	120.00 ¹¹
8	To apply undercoating.	\$	200.00 ⁸⁰
9	Panel beating.	\$	1,800.00 ⁸⁵⁰
10	To re-spray painting on the affected areas.	\$	1,600.00 ¹⁰⁰⁰
		\$	4,520.00

GRAND TOTAL :

\$ 13,990.60

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2999.9
202
P-2399.92
C.N-340
L-2270
5009.92