



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2200111

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 06/01/2022
Reference CC6/CTI21011734/Ups3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SKZ 2636K
Insured Veh. SLP 2994S
Claim No. SNM21D206586/C02
Policy No. DMPCSNW00097242100
Accident Date 13/11/2021
Inspection Date 17/11/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21011734/Ups3q2 Date: 06/01/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLP 2994S	Veh. Inspected	SKZ 2636K
	Policy No.	DMPCSNW00097242100	Coverage (\$)	0.00
	Claim No.	SNM21D206586/C02	Excess (\$)	0.00
	Assign From		Assign Date	17/11/2021
2. Vehicle Particulars & Condition				
	Make & Model	AUDI A6 (A)	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	WAUZZZ4GXGN103672	Colour	SILVER
	Odometer	119498 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/55 R17	PIRENZA	6 mm
	L/H Front Tyre	225/55 R17	PIRELLI	6 mm
	R/H Rear Tyre	225/55 R17	PIRELLI	6 mm
	L/H Rear Tyre	225/55 R17	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/11/2021	Inspection Date	17/11/2021
	Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 2636K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEEP CUT / DEFORMED	2,347.38	2,347.38
2	REAR BUMPER SIDE RETAINER RH/LH @\$110.25	NOT NECESSARY	220.50	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	2,860.93	-
1	REAR SPORT WHEEL	WARPED	1,577.38	1,295.00
1	REAR SHOCK ABSORBER LH	NOT NECESSARY	660.92	-
1	REAR TOP ARM	NOT NECESSARY	665.86	-
1	REAR CAMBER STRUT	NOT NECESSARY	460.90	-
1	REAR LOWER CONTROL ARM	NOT NECESSARY	1,017.94	-
1	REAR KNUCKLE ARM	BENT	1,200.26	993.00
1	REAR WHEEL HUB BEARING	DAMAGED	530.51	530.51
	LESS 5% DISCOUNT		-577.13	-258.29
			10,965.45	4,907.60
	<u>SPECIAL NETT ITEMS</u>			
1	REYAR TYRE LH (SN)	SERVICEABLE	450.00	-
			450.00	-
	<u>LABOUR</u>			
	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT.		120.00	80.00
	TO REMOVE & REPLACE REAR UNDERCARRIAGE PARTS.		300.00	150.00
	TO PUTTY ,SPRAY PAINT & POLISH AFFECTED PARTS .		800.00	300.00
	TO PANEL BEAT,CUT ,WELD ,REMOVE & REPLACE DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER LH .		600.00	400.00
			1,820.00	930.00
	GRAND TOTAL		13,235.45	5,837.60

Report Ref No. CC6/CTI21011734/Ups3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,650.00
---	--	--	-----------------

Report Ref No. CC6/CTI21011734/Ups3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKZ 2636K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKZ 2636K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKZ 2636K

RE-INSPECTION

