

AIG

Vehicle number	SJU2295Z
Make / Model	LEXUS RX300
Chassis number	ACU300074372
Accident date	3/11/21
Reference	2111-17

Qty	Particulars	Unit Price - SGD \$	
PARTS REPLACEMENT - LIST ITEMS			
1	REAR BUMPER / <i>de</i>	1023.00	✓
2	REAR BUMPER RETAINER / <i>de</i>	209.00	137
1	REAR BUMPER REFLECTOR LH / <i>✓</i> CRA	269.50	87.1
1	REAR BUMPER REINFORCEMENT / <i>✓</i> BR	1061.50	329.3
1	REAR BUMPER SPONGE / <i>✓</i> CRA	209.00	111
1	TAILGATE / <i>face</i>	1496.00	✓
1	TAILGATE RUBBER / <i>hri</i>	478.50	194.1
1	TAILGATE LAMP LH / <i>✓</i> BR	247.50	191
1	TAILGATE LOCK / <i>Cut</i>	649.00	226
1	TAILGATE LOCK STRIKER X <i>nn</i>	159.00	
1	TAILGATE INNER TRIM BOARD / <i>✓</i> BR	628.10	485
1	TAILGATE OUTER CHROME GARNISH / <i>✓</i> BR	264.00	✓
1	TAILGATE EMBLEM - LOGO / <i>---</i>	118.80	✓
1	TAILGATE EMBLEM - LEXUS / <i>---</i>	97.90	✓
1	TAILGATE EMBLEM - RX300 / <i>---</i>	104.50	✓
1	TAILGATE GLASS MOULDING / <i>---</i>	104.50	✓
1	WIPER MOTOR X <i>nn</i>	447.70	
1	END PANEL X Repair	874.50	
1	END PANEL TOP GARNISH / <i>✓</i> CRA	313.50	✓
		8755.50	5282.7
Less 25%		2188.88	
		6566.62	3962.02
PARTS REPLACEMENT - SPECIAL NETT ITEMS			
1 SET	REAR BUMPER CLIP / <i>---</i>	30.00	✓
1 SET	TAILGATE INNER TRIM CLIP / <i>---</i>	50.00	30
1 SET	END PANEL INNER TRIM CLIP / <i>---</i>	50.00	20
1	REAR BUMPER TOP RUBBER / <i>---</i>	200.00	100
1	WINDSCREEN SEALNT / <i>---</i>	120.00	40
1 SET	REVERSE SENSOR / <i>nn</i>	300.00	200
1 SET	JOINT SEALANT X NN	150.00	
Subtotal		900.00	420
Balance C/F		7466.62	

<u>LABOUR AND MISCELLANEOUS CHARGES</u>			
1	CHECK WIRING AND LIGHTNING SYSTEM	60.00	30
2	R & R TRIMS AND GARNISHES TO FACILITATE REPAIR	150.00	60
3	R & R REVERSE SENSOR	150.00	40
4	R & R WINDSCREEN GLASS	180.00	120
5	TRANSFER TAILGATE MECHANISM TO FACILITATE REPAIR	150.00	60
6	PANEL BEATING ON AFFECTED AREAS	1400.00	400 ? 500
7	SPRAY PAINTING ON AFFECTED AREAS	1400.00	400 ? 600
8	APPLY ANTI RUST ON AFFECTED AREAS	150.00	X NN
Subtotal		3640.00	1410
Grand total		11106.62	

5792.02

-20%: 4600

4 Days.

4s

After repair photos.

photo

Geo Ring

18/11/21.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price must be subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplemental work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: