

COMFORTBELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Vehicle No.: SHC2057M
Make : TOYOTA
Model : PRIUS
DOA : 16.11.2021

Date : 16.11.2021
Insurance:
MVA : CHIANG

AIG

Part No.	Parts Description / Labour	Qty	Unit Price	Amount
				\$950.50
1	BONNET <i>X repair</i>			\$87.70
1	BONNET HINGE /LH <i>X Snn</i>			\$438.00
1	RADIATOR GRILLE <i>X Snn</i>			\$88.00
1	RADIATOR GRILLE EMBLEM <i>/ all</i>			\$920.00
1	LAMP ASSY, FOG, /LH <i>/ Dis.</i>			\$499.90
1	FRONT BUMPER COVER			\$696.40
1	FRONT BUMPER REINFORCEMENT <i>X Snn</i>			\$301.90
1	FRONT BUMPER CENTRE GRILLE <i>X</i>			\$22.00
10	FRONT BUMPER CLIPS <i>/ all - Dis.</i>			\$77.00
1	FRONT BUMPER SIDE RETAINER /LH <i>?</i>			\$28.38
1	COVER, FRONT BUMPER HOLE, RH /LH <i>?</i>			\$82.30
1	BRACKET, FRONT BUMPER SIDE, RH /LH <i>?</i>			\$127.70
1	ABSORBER, FRONT BUMPER, LOWER (SPONGE LOWER) <i>X nn</i>			\$2,637.60
1	UNIT ASSY, HEADLAMP, /LH (LED) <i>/ CAA</i>			\$240.10
1	HEAD LAMP PANEL /LH <i>??</i>			\$364.90
1	TOP PANEL CENTRE <i>??</i>			\$145.90
1	TOP PANEL SIDE <i>??</i>			\$25.50
1	BRACKET, HEADLAMP MOUNTING, /LH <i>?</i>			\$1,841.80
1	RADIATOR ASSY <i>?</i>			\$661.30
1	RADIATOR FAN COWLING ASSY <i>?</i>			\$125.80
1	RADIATOR SPARE TANK <i>X X Snn</i>			\$210.00
1	SUPPRT LOWER RADIATOR <i>X</i>			\$174.20
2	STAY, RADIATOR SUPPORT, RH /LH <i>X</i>		\$81.70	\$945.30
1	FENDER SUB-ASSY, FRONT /LH <i>/ Duc</i>			\$958.30
1	FRONT HOUSING ASSY, LH <i>X repair</i>			\$196.60
1	FRONT FENDER SHIELD, /LH <i>/ all</i>			\$53.50
2	FRONT FENDER HYBRID EMBLEM, RH /LH <i>/ all</i>		\$53.50	\$96.00
1	FRONT PILLAR UPPER COVER, LH <i>/ mis.</i>			\$1,728.70
1	FRONT LH WING MIRROR ASSY <i>/ Dis</i>			\$141.90
1	FRONT OUTER MIRROR COVER <i>/ mis</i>			\$668.32
1	WIPER TOP GARNISH <i>?</i>			\$1,555.10
1	FRONT WHEEL RIM (LH/) <i>/ cut</i>			\$560.10
1	FRONT WHEEL HUB BEARING (LH/) <i>?</i>			\$401.80
1	FRONT SHOCK ABSORBER (LH) <i>?</i>			\$196.20
1	ABSORBER TOP MOUNTING, LH <i>X nn</i>			\$637.50
1	FRONT SUSPENSION LOWER ARM (LH) <i>?</i>			\$1,634.90
1	RACK & PINION ASSY <i>X nn</i>			\$562.30
1	KNUCKLE, STEERING, LH <i>?</i>			\$202.40
1	JOINT ASSY, LOWER BALL, FRONT LH <i>?</i>			\$549.70
1	HUB SUB-ASSY, FRONT AXLE, /LH <i>X Snn</i>			\$158.10
1	END SUB-ASSY, TIE ROD, LH <i>X</i>			\$457.20
1	ENGINE UNDER COVER <i>?</i>			\$1,264.00
1	FRONT DOOR PANEL <i>/ Dmc</i>			\$313.60
1	FRONT DOOR GLASS LH <i>/ CAA</i>			

Part No.	Parts Description / Labour	Qty	Unit Price	Amount
	SUB TOTAL			\$24,028.40
	LESS 25%			\$6,007.10
	DISCOUNTED TOTAL			\$18,021.30
	REAR DOOR COMFORT APP <i>/ Gate</i>			\$80.00
	FRONT DOOR COMFORT LOGO			\$75.00
	FRONT TYRE (LH/)			\$216.00
				\$371.00
	<u>Labour Charge</u>			\$1,600.00
	Panel Beating			\$800.00
	Spray Painting Charge			\$120.00
	Wiring Charge			\$50.00
	Tuff Kote			\$60.00
	Towing Charge			\$90.00
	Transfer of Door			\$90.00
	FRT Wheel Alignment			
	TOTAL LABOUR			\$2,810.00
	ESTIMATE TOTAL			\$21,202.30
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

1850
 750
 32
 ✓
 60
 60

6 Days.
 Lampson Repair
 After repair photos.
 Gino Aziz
 18/11/21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damage & part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary work must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: