

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 199607198R GST Reg. No. 19-9607198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref	CS/AGI21011742/Utf3n2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date	e: 03/12/2021	
			Cod	le: AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLM 6721C	Veh. Inspected	SJL 6073T	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10012525/EE	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	17/11/2021	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA COROLLA ALTIS (A)	C.C	1598	
	Engine No.	HIDDEN	Year of Reg.	2008	
	Chassis No.	MR053ZEE106122228	Colour	GREY	
	Odometer	164091 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	YOKOHAMA	7 mm	
	L/H Front Tyre	195/65 R15	YOKOHAMA	7 mm	
	R/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm	
	L/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	17/11/2021	Inspection Date	18/11/2021	
	Survey held at	FASTECH AUTO PTE LTD			
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a.	a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	5b. Estimate Days of Repair				

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: