

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : Peck Zi Qiang (92335554,
84992650)

Accident Date : 14-Nov-21

Suzuki

UH200AL6

Vehicle No : FBQ3680D

Vehicle Model : Burgman 200
ABS

Estimated Repair Costs

Qty	Description	Amount S(\$)
	List Items	
1	Front fender <i>cut</i>	\$ 155.00 <i>✓</i>
1	Front fairing <i>one</i>	\$ 450.00 <i>✓</i>
1	Front fairing inner panel <i>one</i>	\$ 265.00 <i>✓</i>
1	Front lower fairing <i>one</i>	\$ 210.00 <i>✓</i>
1	Lower belly panel <i>cut</i>	\$ 285.00 <i>✓</i>
1	Headlamp <i>one</i>	\$ 525.00 <i>✓</i>
1	Headlamp cover <i>one</i>	\$ 155.00 <i>✓</i>
2	Front signals <i>3ea/one o/s</i>	\$ 310.00 <i>to C</i>
1	Front fork assy <i>2</i>	\$ 850.00 <i>X</i>
1	Fork under bracket <i>2ea</i>	\$ 220.00 <i>X</i>
1	Front rim <i>2</i>	\$ 310.00 <i>X</i>
1	Front brake disc <i>11</i>	\$ 165.00 <i>X</i>
1	Front rim shaft <i>11</i>	\$ 78.00 <i>X</i>
1	Front rim bearing <i>11</i>	\$ 65.00 <i>X</i>
1	Windshield <i>cut</i>	\$ 285.00 <i>✓</i>
1	Windshield inner cover <i>one</i>	\$ 150.00 <i>✓</i>
2	Side mirrors <i>1/5 cut 0/5 11</i>	\$ 160.00 <i>1/2</i>
1	Handle bar <i>2ea</i>	\$ 165.00 <i>2</i>
2	Handle bar ends <i>2ea</i>	\$ 80.00 <i>X</i>
2	Hand grips <i>11</i>	\$ 80.00 <i>X</i>
2	Brake levers <i>1/5 cut 0/5 11</i>	\$ 168.00 <i>1/2</i>
1	Rear fairing - R/H <i>one</i>	\$ 355.00 <i>✓</i>
2	Footstep panel <i>1/5 cut 0/5 11 X</i>	\$ 220.00 <i>1/2</i>
2	Footstep lower panel <i>1/5 cut 0/5 11 X</i>	\$ 350.00 <i>1/2</i>
1	Exhaust assy <i>2ea/2ea</i>	\$ 890.00 <i>✓</i>
1	Exhaust protector <i>Dis</i>	\$ 120.00 <i>✓</i>
1	Exhaust end cap <i>one</i>	\$ 98.00 <i>✓</i>
1	Exhaust bracket <i>one</i>	\$ 285.00 <i>✓</i>
1	Rear lamp assy <i>11</i>	\$ 385.00 <i>X</i>
1	Rear absorber <i>2ea</i>	\$ 585.00 <i>✓</i>
1	Engine mounting <i>11</i>	\$ 385.00 <i>X</i>
1	Belt cover <i>cut</i>	\$ 185.00 <i>✓</i>
		\$ 8,989.00
	Less 10%	\$ 898.90
		\$ 8,090.10

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : Peck Zi Qiang (92335554,
84992650)

Accident Date : 14-Nov-21

Suzuki

UH200AL6

Vehicle No : FBQ3680D

Vehicle Model : Burgman 200
ABS

Estimated Repair Costs

Special Net Items

1	Number plate (1 set)	for net	\$	38.00	10
2	Fork oils	17	\$	30.00	X
2	Fork oil seals	17	\$	56.00	X
1	Steering cone (1 set)	17	\$	90.00	X
1	Rear box	Dis	\$	380.00	280
1	Rear box bracket	Ref	\$	180.00	150
1	Sticker	net	\$	120.00	✓
			\$	894.00	

in unit

one 17500
165 s/w

S/No. Labour

1	To provide towing service (LOD)	\$	60.00	50
2	To check wiring and reset headlamp focusing	\$	80.00	X
3	To provide labour	\$	420.00	350
4	To repair body frame	\$	480.00	X
5	To respray painting	\$	600.00	80
			<u>\$</u>	<u>1,640.00</u>

Grand Total

\$ 10,624.10

Singapore Dollars: Ten Thousand Six Hundred and Twenty-Four and Cents: Ten only

EROFIA MOTOR TRADING PTE LTD

ERK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

7015-7