

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : Peck Zi Qiang (92335554,
84992650)

Accident Date : 14-Nov-21

Vehicle No : FBQ3680D

Suzuki
UH200AL6
Vehicle Model : Burgman 200
ABS

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender <i>cu7</i>	\$ 155.00 —
1	Front fairing <i>one</i>	\$ 450.00 —
1	Front fairing inner panel <i>one</i>	\$ 265.00 —
1	Front lower fairing <i>one</i>	\$ 210.00 —
1	Lower belly panel <i>cu7</i>	\$ 285.00 —
1	Headlamp	\$ 525.00 ?
1	Headlamp cover <i>m.s</i>	\$ 155.00 —
2	Front signals ?	\$ 310.00 ?
1	Front fork assy <i>n</i>	\$ 850.00 X
1	Fork under bracket <i>SLC</i>	\$ 220.00 X
1	Front rim <i>n</i>	\$ 310.00 X
1	Front brake disc <i>11</i>	\$ 165.00 X
1	Front rim shaft <i>11</i>	\$ 78.00 X
1	Front rim bearing <i>11</i>	\$ 65.00 X
1	Windshield <i>cu7</i>	\$ 285.00 —
1	Windshield inner cover <i>one</i>	\$ 150.00 —
2	Side mirrors <i>n/s cu7 0/5 n</i>	\$ 160.00 <i>1pc</i>
1	Handle bar	\$ 165.00 ?
2	Handle bar ends <i>SLC</i>	\$ 80.00 X
2	Hand grips <i>11</i>	\$ 80.00 X
2	Brake levers <i>n/s cu7 0/5 n</i>	\$ 168.00 <i>1pc</i>
1	Rear fairing - R/H <i>one</i>	\$ 355.00 —
2	Footstep panel <i>n/s cu7 0/5 ?</i>	\$ 220.00 <i>1pc</i>
2	Footstep lower panel <i>n/s cu7 0/5 ?</i>	\$ 350.00 <i>1pc</i>
1	Exhaust assy <i>100 / dent</i>	\$ 890.00 —
1	Exhaust protector <i>D.S</i>	\$ 120.00 —
1	Exhaust end cap <i>one</i>	\$ 98.00 —
1	Exhaust bracket <i>one</i>	\$ 285.00 —
1	Rear lamp assy	\$ 385.00 ?
1	Rear absorber	\$ 585.00 ?
1	Engine mounting	\$ 385.00 ?
1	Belt cover <i>cu7</i>	\$ 185.00 —
		\$ 8,989.00
	Less 10%	\$ 898.90
		\$ 8,090.10

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : Peck Zi Qiang (92335554,
84992650)

Accident Date : 14-Nov-21

Vehicle No : FBQ3680D

Suzuki
UH200AL6
Vehicle Model : Burgman 200
ABS

Estimated Repair Costs

Special Net Items

1	Number plate (1 set)	for net	\$	38.00	10
2	Fork oils	17	\$	30.00	X
2	Fork oil seals	17	\$	56.00	X
1	Steering cone (1 set)	17	\$	90.00	X
1	Rear box	7.5	\$	380.00	280
1	Rear box bracket	for	\$	180.00	150
1	Sticker	net	\$	120.00	✓
			\$	894.00	
	14 ERP				
					17500
					1655/n

S/No. Labour

1	To provide towing service (LOD)	\$	60.00	50
2	To check wiring and reset headlamp focusing	\$	80.00	X
3	To provide labour	\$	420.00	350
4	To repair body frame	\$	480.00	?
5	To respray painting	\$	600.00	180
		\$	1,640.00	

Grand Total

\$ 10,624.10

Singapore Dollars: Ten Thousand Six Hundred and Twenty-Four and Cents: Ten only

EROFIA MOTOR TRADING PTE LTD

EROFIA Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: