

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : IDI QALIF BIN TAHA
BLK 648 PUNGGOL CENTRAL
#06-382
SINGAPORE 820648

Claim No: MC1902271
No: MF1902109
Date: 23 Feb 2022
Policy No: GA486579/1
Veh Reg No: SJS3879T
Make/Model: MERCEDES R280L
Chassis No: WDC2511542A098796
TP Ins Co: CHINA

ATTN:
Your Ref No: SNM21D206483C02
Claim Type: Third Party
Accident Date: 11/11/2021
TP Veh Reg No: GBG7411R

Repair Cost to Vehicle No (For Finalization):SJS3879T

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 PARK LAMP RH	1 PC	120.00	
2 FRONT BUMPER RIVETS	10 PC	30.00	
3 PARKIUNG SENSOR RING	6 PC	42.00	
4 REAR BUMPER	1 PC	1,800.00	
5 REAR BUMPER LOWER GARNISH	1 PC	680.00	
6 REAR BUMPER TOP PLATE	1 PC	405.00	
7 REAR BUMPER RIVETS	10 PC	30.00	
8 REVERSE SENSOR RING	4 PC	28.00	
		3,135.00	
	Less 10%	313.50	2,821.50
Special Nett			
9 NUMBER PLATE	1 PC	35.00	
		35.00	35.00
LABOUR			
10 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	
11 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	
12 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	30.00	
13 TO DISMANTLE ALL DAMAGED PARTS.TO KNOCK & REPAIR , REAR END PANEL. INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	
14 TO SPRAY FRONT BUMPER, REAR BUMPRER, REAR END PANEL	1 PC	440.00	
		1,070.00	1,070.00

AH LIM MOTOR COMPANY
(SIN LING DRAUGHT)
170, Serangoon Road, #05-12
Singapore 550170
Tel: 6483 3837 Fax: 6483 3838

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : IDI QALIF BIN TAHA
BLK 648 PUNGGOL CENTRAL
#06-382
SINGAPORE 820648

Claim No: MC1902271
No: MF1902109
Date: 23 Feb 2022
Policy No: GA486579/1
Veh Reg No: SJS3879T
Make/Model: MERCEDES R280L
Chassis No: WDC2511542A098796
TP Ins Co: CHINA

ATTN:
Your Ref No: SNM21D206483C02
Claim Type: Third Party
Accident Date: 11/11/2021
TP Veh Reg No: GBG7411R

Repair Cost to Vehicle No (For Finalization):SJS3879T

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	Total		S\$ 3,926.50
	Lump Sum Less 20%		-785.30
	Sub Total		S\$ 3,141.20
	Less Rounding		-41.20
	Lum Sum Repair		S\$ 3,100.00
	Add GST @ 7%		217.00
	Total Amount Payable		<u>S\$ 3,317.00</u>

TOTAL: SINGAPORE DOLLAR THREE THOUSAND THREE HUNDRED SEVENTEEN ONLY

The above vehicle was surveyed by STEVE - LKK on 18/11/2021

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
(06) 6483 1244
177 Ang Mo Kio Street, #05-12
Ang Mo Kio Autopoint Singapore 570721
AUTHORISED SIGNATURE
Tel: 6483 3337 Fax: 6483 3336

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : IDI QALIF BIN TAHA
BLK 648 PUNGGOL CENTRAL
#06-382
SINGAPORE 820648

Estimate No: MC1902271
Date: 11 Nov 2021
Policy No: GA486579/1
Veh Reg No: SJS3879T
Make/Model: MERCEDES R280L

ATTN:
Your Ref No: -
Claim Type: Third Party
Accident Date: 11/11/2021
TP Veh Reg No: GBG7411R

1130.
Resurveyed by Kenneth @ 2:10 pm
13 Jan 2022.
He refused to write anything down...

Estimate Repair Cost to Vehicle No :SJS3879T

Description

Quantity

Nett

List Price
S\$

Amount
S\$

SPARE PARTS

1- HEADLAMP RH	1 PC	1,250.00	
2 PARK LAMP RH	1 PC	120.00	
3 FRONT BUMPER	1 PC	2,150.00	
4 FRONT BUMPER NUMBER PLATE GARNISH	1 PC	290.00	
5 FRONT BUMPER INNER BOX	1 PC	310.00	
6 FRONT BUMPER SPONGE CENTRE	1 PC	280.00	
7 FRONT BUMPER REINFORCEMENT	1 PC	1,180.00	
8 FRONT BUMPER SIDE RETAINER LH / RH	2 PC	130.00	
9 FRONT BUMPER RIVETS	10 PC	70.00	
10 PARKING SENSOR CENTRE LH / RH	2 PC	410.00	
11 PARKING SENSOR RING	6 PC	42.00	
12 REAR BUMPER	1 PC	1,800.00	
13 REAR BUMPER LOWER GARNISH	1 PC	680.00	
14 REAR BUMPER TOP PLATE (chrom)	1 PC	405.00	
15 REAR BUMPER SIDE RETAINER LH / RH	2 PC	80.00	
16 REAR BUMPER RIVETS	10 PC	70.00	
17 REVERSE SENSOR CENTRE LH & RH	2 PC	410.00	
18 REVERSE SENSOR RING	4 PC	28.00	
19 REAR BUMPER SUPPORT	1 PC	440.00	

10,145.00

Less 10%

1,014.50

9,130.50

Special Nett

20 NUMBER PLATE	1 PC	35.00	
		35.00	35.00

LABOUR

21 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	
22 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	2 PC	120.00	60
23 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	30
24 TO DISMANTLE ALL DAMAGED PARTS TO KNOCK & REPAIR, REAR END PANEL. INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	700.00	500
25 TO SPRAY FRONT BUMPER, REAR BUMPER, REAR END PANEL	1 PC	700.00	440
		1,620.00	1,620.00

13-01-22
Siong

Order
29-12-21
Cur pass

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : IDI QALIF BIN TAHA
BLK 648 PUNGGOL CENTRAL
#06-382
SINGAPORE 820648

Estimate No: MC1902271
Date: 11 Nov 2021
Policy No: GA486579/1
Veh Reg No: SJS3879T
Make/Model: MERCEDES R280L

ATTN:
Your Ref No: -
Claim Type: Third Party
Accident Date: 11/11/2021
TP Veh Reg No: GBG7411R

Estimate Repair Cost to Vehicle No :SJS3879T

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		Total	S\$ 10,785.50
		Add GST @ 7%	754.99
		Total Amount Payable	S\$ 11,540.49

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND FIVE HUNDRED FORTY AND CENTS FORTY NINE ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

Steve (LKK) ML AL
8322 8813 L/S
M AL M
\$4 djs

For AH LIM MOTOR COMPANY


AUTHORISED SIGNATURE