

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimm@singnet.com.sg
 GST:M9-0009639-E RCB NO.06470300B

Jan 1 82834156

M/S : IDI QALIF BIN TAHA
 BLK 648 PUNGGOL CENTRAL
 #06-382
 SINGAPORE 820648

Estimate No: MC1902271
 Date: 11 Nov 2021
 Policy No: GA486579/1
 Veh Reg No: SJS3879T
 Make/Model: MERCEDES R280L

1130.

ATTN:
 Your Ref No: -
 Claim Type: Third Party
 Accident Date: 11/11/2021
 TP Veh Reg No: GBG7411R

Estimate Repair Cost to Vehicle No :SJS3879T

Description	Quantity	List Price SS	Amount SS
SPARE PARTS			
1 HEADLAMP RH ? x nn	1 PC	1,250.00	
2 PARK LAMP RH - BR	1 PC	120.00	
3 FRONT BUMPER x R	1 PC	2,150.00	
4 FRONT BUMPER NUMBER PLATE GARNISH ? x nn	1 PC	290.00	
5 FRONT BUMPER INNER BOX ? x nn	1 PC	310.00	
6 FRONT BUMPER SPONGE CENTRE ? x nn	1 PC	280.00	
7 FRONT BUMPER REINFORCEMENT x nn	1 PC	1,180.00	
8 FRONT BUMPER SIDE RETAINER LH / RH ? x nn	2 PC	130.00	
9 FRONT BUMPER RIVETS - nrc	10 PC	70.00	
10 PARKING SENSOR CENTRE LH / RH BR ? x nn	2 PC	410.00	
11 PARKING SENSOR RING - nrc	6 PC	42.00	
12 REAR BUMPER - CRU	1 PC	1,800.00	
13 REAR BUMPER LOWER GARNISH - CUT	1 PC	680.00	
14 REAR BUMPER TOP PLATE (chrom) - DO	1 PC	405.00	
15 REAR BUMPER SIDE RETAINER LH / RH ? x nn	2 PC	80.00	
16 REAR BUMPER RIVETS - nrc	10 PC	70.00	
17 REVERSE SENSOR CENTRE LH & RH ? x nn	2 PC	410.00	
18 REVERSE SENSOR RING - nrc	4 PC	28.00	
19 REAR BUMPER SUPPORT ? x nn	1 PC	440.00	
Rear bumper Tan Cover		10,145.00	
	Less 10%	1,014.50	9,130.50
Special Nett			
20 NUMBER PLATE - BR	1 PC	35.00	
		35.00	35.00
LABOUR			
21 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	
22 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	2 PC	120.00	60
23 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	30
24 TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR, REAR END PANEL. INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	700.00	500
25 TO SPRAY FRONT BUMPER, REAR BUMPER, REAR END PANEL	1 PC	700.00	440
		1,620.00	1,620.00
			= 3926.50

L/S - 3141.20
 = 3100

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : IDI QALIF BIN TAHA
BLK 648 PUNGGOL CENTRAL
#06-382
SINGAPORE 820648

Estimate No: MC1902271
Date: 11 Nov 2021
Policy No: GA486579/1
Veh Reg No: SJS3879T
Make/Model: MERCEDES R280L

ATTN:
Your Ref No: -
Claim Type: Third Party
Accident Date: 11/11/2021
TP Veh Reg No: GBG7411R

Estimate Repair Cost to Vehicle No :SJS3879T

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		Total	S\$ 10,785.50
		Add GST @ 7%	754.99
		Total Amount Payable	S\$ 11,540.49


TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND FIVE HUNDRED FORTY AND CENTS FORTY NINE ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

Steve (LKK) ML AL
8322 8813 L/S
M AL Ly
\$4 dys

For AH LIM MOTOR COMPANY


No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244
AUTHORISED SIGNATURE