



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2203978

36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV Date 27/06/2022  
Reference CC4/FCI21011747/Uga3q2  
Code FCI2

#### PROFESSIONAL SERVICE FEE

Vehicle No. FBF 7963U  
Insured Veh. GBG 7643M  
Claim No. D21003204MFCV  
Policy No.  
Accident Date 06/11/2021  
Inspection Date 17/11/2021

Description	Total
Survey Inspection	211.00
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>211.00</b>
<b>GST (7%)</b>	<b>14.77</b>
<b>Grand Total</b>	<b>225.77</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Ref: CC4/FCI21011747/Uga3q2

Date: 27/06/2022

Code: FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GBG 7643M	<b>Veh. Inspected</b>	FBF 7963U
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	D21003204MFCV	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	CHRIS	<b>Assign Date</b>	17/11/2021

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	SYM FIGHTER 150	<b>c.c</b>	150
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2011
<b>Chassis No.</b>	RFGHV1SV0BS000071	<b>Colour</b>	WHITE
<b>Odometer</b>	36529 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	120/70-12	KENDA	6 mm
<b>L/H Front Tyre</b>			mm
<b>R/H Rear Tyre</b>	120/70-12	KENDA	6 mm
<b>L/H Rear Tyre</b>			mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	06/11/2021	<b>Inspection Date</b>	17/11/2021
<b>Survey held at</b>	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBF 7963U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	COVER FRONT (CUT)	NOT CONSISTENT WITH THE IMPACT	155.00	-
1	COVER SIDE LH ASSY (WHITE)(CUT)	NOT CONSISTENT WITH THE IMPACT	82.00	-
1	COVER TOP (CUT)	NOT CONSISTENT WITH THE IMPACT	94.00	-
1	COWLING FRONT (WHITE)	NOT NECESSARY	168.00	-
1	FORK FRONT LH ASSY	NOT NECESSARY	350.00	-
1	GASKET EXHAUST PIPE	NOT NECESSARY	9.00	-
1	HEADLAMP ASSY LH	NOT NECESSARY	287.00	-
1	HEADLAMP ASSY RH	NOT NECESSARY	287.00	-
1	LEVER BRAKE LH (SCRATCHED)	NOT CONSISTENT WITH THE IMPACT	25.00	-
1	LEVER BRAKE RH (SCRATCHED)	NOT CONSISTENT WITH THE IMPACT	27.00	-
1	METER VISOR ASSY BU-661S	NOT NECESSARY	84.00	-
1	MIRROR ASSY LH	NOT NECESSARY	68.00	-
1	MIRROR RH	NOT NECESSARY	70.00	-
1	MUDGUARD REAR	BROKEN	32.00	32.00
1	PIPE EXHAUST ASSY	NOT NECESSARY	645.00	-
1	PROTECTOR CLUTCH COVER	NOT NECESSARY	59.00	-
1	PROTECTOR MUFFLER (SCRATCHED)	NOT CONSISTENT WITH THE IMPACT	43.00	-
1	R SIDE COVER ASSY WH-010C/BK-001U	NOT NECESSARY	73.00	-
1	SPOILER UNDER (CUT)	NOT CONSISTENT WITH THE IMPACT	147.00	-
1	STICKER (SINGAPORE POST) BOX REAR	NOT NECESSARY	70.00	-
	LESS 10% DISCOUNT		-	-3.20
			2,775.00	28.80
<b>SPECIAL NETT ITEMS</b>				
1	PLATE NUMBER REAR (6.5 INCH X 9 INCH)(SN)	BENT	27.00	15.00
			27.00	15.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	LABOUR-LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.		504.00	180.00
	SPRAY PAINT ON REAR BOX.	NOT NECESSARY	250.00	-
	TRANSPORT CHARGES-BIKE TOWED BACK TO BHH.	NOT NECESSARY	55.00	-
			809.00	180.00
	<b>GRAND TOTAL</b>		<b>3,611.00</b>	<b>223.80</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>223.80</b>

Report Ref No. CC4/FCI21011747/Uga3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBF 7963U

INSPECTION






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

