



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2301208

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 01/03/2023
Reference CC3/CTI21011748/Apa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMU 7868C
Insured Veh. GBL 5822A
Claim No. SNM21D206464/C02/KHONGLH
Policy No. DMCVSNW00136472100
Accident Date 09/11/2021
Inspection Date 16/11/2021

Description	Total
Survey Inspection	280.00
Digital Photographs	
Transportation	
Subtotal	280.00
GST (8%)	22.40
Grand Total	302.40

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI21011748/Apa3q2	
			Date: 01/03/2023	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBL 5822A	Veh. Inspected	SMU 7868C	
Policy No.	DMCVSNW00136472100	Coverage (\$)	0.00	
Claim No.	SNM21D206464/C02/KHONGL H	Excess (\$)	0.00	
Assign From		Assign Date	16/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	AUDI Q3	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	WAUZZZF3XL1116157	Colour	GREY	
Odometer	10422 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/65 R17	FALKEN	6 mm	
L/H Front Tyre	215/65 R17	FALKEN	6 mm	
R/H Rear Tyre	215/65 R17	FALKEN	6 mm	
L/H Rear Tyre	215/65 R17	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/11/2021	Inspection Date	16/11/2021	
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMU 7868C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (SN)	TO REPAIR SEE LABOUR	1,634.00	-
1	REAR BUMPER FIXING PARTS (SN)	NOT NECESSARY	211.00	-
1	REAR BUMPER SPOILER (SN)	CUT	459.00	459.00
1	REAR LIGHT REFLECTOR -RH (SN)	NOT NECESSARY	41.00	-
1	LED TAIL LIGHT -RH (SN)	NOT NECESSARY	926.00	-
1	REAR BUMPER GUIDE SECTION -RH (SN)	NOT NECESSARY	63.00	-
2	REAR WHEEL ARCH COVER -LH/RH (SN)	N/S NECESSARY / O/S CUT	536.00	536.00
1	REAR DOOR -RH (SN)	DENTED	2,909.00	2,909.00
1	REAR OUTER DOOR SEAL -RH (SN)	NECESSARY	135.00	135.00
1	REAR DOOR CATCH -RH (SN)	* CHECK	120.00	-
1	REAR DOOR HANDLE ,EXTERIOR -RH (SN)	TO REPAIR SEE LABOUR	198.00	-
1	REAR DOOR HANDLE CAP -RH (SN)	NOT NECESSARY	27.00	-
1	REAR DOOR COVER -RH (SN)	NECESSARY	257.00	257.00
1	REAR ALUMINIUM RIM -RH (SN)	CUT	1,262.00	1,262.00
1	REAR WHEEL HOUSING LINER -RH (SN)	NOT NECESSARY	241.00	-
1	REAR UNDERBODY TRIM -RH (SN)	NOT NECESSARY	52.00	-
1	METAL FILLER POWDER (SN)	NOT NECESSARY	280.00	-
1	STONE CHIP (SN)	NOT NECESSARY	180.00	-
1	SUNDRIES (SN)	* CHECK	300.00	-
			9,831.00	5,558.00
<u>LABOUR</u>				
TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR ,CHECK FUNCTION .			360.00	360.00
TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER MODULE DEVICES .INSPECT FOR DAMAGES.			400.00	400.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR.TO REPAIR RHS REAR FENDER REORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR DOOR HANDLE ,EXTERIOR -RH.		2,800.00	2,000.00
	TO RESPRAY REAR BUMPER ,RHS REAR FENDER AND RHS REAR DOOR .		3,000.00	2,400.00
	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.		280.00	280.00
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00
			7,032.00	5,632.00
GRAND TOTAL			16,863.00	11,190.00
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$420.00 NETT)				11,190.00

Report Ref No. CC3/CTI21011748/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMU 7868C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

