

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

KELVIN ONG JIAN LI
BLK 215 MARSILING LANE #02-814
SINGAPORE 730215

TP Budget Direct.
Denise.

Contact : 98639817

TAX INVOICE

Repair Code : CLM15355

Date in : 16/11/2021

Vehicle Num. : SMW4473S

Model : DAIHATSU MATERIA 1.5L AUTO ABS AIRBAG 2WD

Chassis/Eng# : JDAM402S001012251/2092788

Parts and Labour Assesment

Description of part	Qty	Unit Price	892 Amount
REAR BUMPER <i>Behind</i>	1	1217.80	1,217.80
REAR BUMPER LAMP RH <i>cracked</i>	1	223.60	223.60
REAR BUMPER NUMBER PLATE LAMP L/R <i>New</i>	2	83.90	+ 167.80
REAR BUMPER SIDE RETAINER L/R <i>cracked</i>	2	55.00	✓ 110.00
REAR BUMPER TOW HOOK COVER <i>Regis</i>	1	25.00	+ 25.00
REAR END PANEL <i>Dented</i>	1	791.40	885 791.40
REAR END PANEL TOP GARNISH <i>Behind</i>	1	289.35	✓ 289.35
REAR EXHAUST GASKET <i>New</i>	1	25.00	x 25.00
REAR EXHAUST RUBBER MOUNTING <i>New</i>	2	63.90	x 127.80
REAR EXHAUST SILENCER BOX <i>Regis</i>	1	450.00	+ 450.00
REAR FLOOR PANEL <i>Regis</i>	1	786.40	+ 786.40
REAR FLOOR PANEL COMPARTMENT TRAY <i>cracked</i>	1	369.20	✓ 369.20
REAR FLOOR PANEL TOP BOARD COVER <i>Behind</i>	1	389.60	255 389.60
REAR RH FENDER INNER TRIM GARNISH <i>Behind</i>	1	561.40	305 561.40
REAR SPARE TYRE SCREW LOCK <i>New</i>	1	38.00	x 38.00
REAR TAILGATE <i>Dented</i>	1	850.00	✓ 850.00
REAR TAILGATE 'LOGO' EMBLEM <i>New</i>	1	68.00	✓ 68.00
REAR TAILGATE INNER AUTO LOCK CONTROL <i>Damaged</i>	1	489.70	398 489.70

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

KELVIN ONG JIAN LI
 BLK 215 MARSILING LANE #02-814
 SINGAPORE 730215

Contact : 98639817

TAX INVOICE

Repair Code : CLM15355

Date in : 16/11/2021

Vehicle Num. : SMW4473S

Model : DAIHATSU MATERIA 1.5L AUTO ABS AIRBAG 2WD

Chassis/Eng# : JDAM402S001012251/2092788

REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R	<i>New</i>	2	43.90	+	87.80
REAR TAILGATE INNER TRIM	<i>Dehd</i>	1	581.80	<i>223</i>	581.80
REAR TAILGATE LOCK STRIKER	<i>New</i>	1	45.00	+	45.00
REAR TAILGATE MECHANISM LOCK	<i>Damd</i>	1	180.00	✓	180.00
REAR TAILGATE OUTER KEY LOCK	<i>New</i>	1	108.70	+	108.70
REAR TAILGATE OUTER KEY LOCK COVER	<i>New</i>	1	69.80	+	69.80
REAR TAILGATE WEATHER STRIP	<i>ut</i>	1	125.00	✓	125.00
REAR TAILGATE WINDSCREEN MOULDING	<i>New</i>	1	90.00	✓	90.00
REAR TAILLAMP L/R	<i>Crashed</i>	2	360.00	<i>518</i>	720.00
Subtotal before discount					8,988.15
Percentage discount 15%					1,348.22
Sub-total 1					7,639.93
REAR BUMPER CLIPS - SET	<i>New</i>	1	50.00	<i>30</i>	50.00
REAR BUMPER NUMBER PLATE	<i>Dehd</i>	1	25.00	✓	25.00
REAR BUMPER NUMBER PLATE HOLDER	<i>Dehd</i>	1	50.00	<i>30</i>	50.00
REAR BUMPER REVERSE SENSOR - SET	<i>Damd</i>	1	250.00	<i>200</i>	250.00
REAR END PANEL TOP GARNISH CLIPS - SET	<i>New</i>	1	30.00	<i>20</i>	30.00
REAR FENDER INNER SHIELD CLIPS L/R - SET	<i>Not Noc</i>	2	30.00	+	60.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

KELVIN ONG JIAN LI
BLK 215 MARSILING LANE #02-814
SINGAPORE 730215

Contact : 98639817

TAX INVOICE

Repair Code : CLM15355
Date in : 16/11/2021
Vehicle Num. : SMW4473S
Model : DAIHATSU MATERIA 1.5L AUTO ABS AIRBAG 2WD
Chassis/Eng# : JDAM402S001012251/2092788

REAR FENDER INNER TRIM BOARD L/R CLIPS - SET	2	50.00	30	100.00
Subtotal before discount				565.00
Percentage discount	0%	335		0.00
Sub-total 2				565.00
Parts-total				8,204.93

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	✓	60.00
To remove, reinstall tailgate windscreen	120 ✓	150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60 ✓	140.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	2160 800 ✓	1,500.00
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	80 ✓	150.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	900 ✓	1,500.00
To apply anti-rust chemical on repaired and replaced panel.	60 ✓	100.00
To remove, reinstall tailgate mechanism and check for function	✓	80.00
Labour Total		3,680.00
Parts & Labour Total		11,884.93

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is a computer-generated document which requires no signature.***
page 3

Adrian
L/S 18/11/21

06 Days

Total: 7238.97

L/S: S.81C

S.81C