



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2111-270
DATE : 17-Nov-2021
POLICY NO. : AUTO&GEN P10262698R02
VEHICLE REG. NO. : SLT8640C
VEHICLE MAKE : PEUGEOT 3008 ACTIVE PURETECH 1.2

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Front Bumper <i>de /</i>	1	\$ 1,980.00	\$ 1,980.00
2	Front Bumper Lower <i>cut /</i>	1	\$ 380.00	\$ 380.00
3	Front Bumper Clips <i>na /</i>	10	\$ 5.00	\$ 50.00
4	Front Bumper Retainer Set <i>?</i>	1	\$ 180.00	\$ 180.00
5	Front Bumper Inner Top Cover <i>con /</i>	1	\$ 400.00	\$ 400.00
6	Front Grille Base <i>?</i>	1	\$ 350.00	\$ 350.00
7	Front Grille (Center) <i>502 /</i>	1	\$ 580.00	\$ 580.00
8	Front Grille Chrome <i>con /</i>	1	\$ 550.00	\$ 550.00
9	Front Emblem <i>na /</i>	1	\$ 180.00	\$ 180.00
10	Front Bumper Top Rubber Seal <i>X</i>	1	\$ 280.00	\$ 280.00
11	Front Bumper Inner Bracket <i>?</i>	1	\$ 400.00	\$ 400.00
12	Front Reinforcement <i>?</i>	1	\$ 980.00	\$ 980.00
13	Front Sponge / Absorber <i>?</i>	1	\$ 220.00	\$ 220.00
14	Front Bumper Lower Grille <i>con /</i>	1	\$ 660.00	\$ 660.00
15	Front Bumper Lower Grille Cover <i>MIS /</i>	1	\$ 580.00	\$ 580.00
16	Front Bumper Lower Extension <i>cut /</i>	1	\$ 280.00	\$ 280.00
17	Head Lamp RH <i>con /</i>	1	\$ 2,200.00	\$ 2,200.00
18	Head Lamp LH <i>con /</i>	1	\$ 2,200.00	\$ 2,200.00
19	Front Ultrasonic Sensor Wiring Harness <i>?</i>	1	\$ 550.00	\$ 550.00
20	Front Ultrasonic Sensor RH @ Grille <i>X</i>	1	\$ 440.00	\$ 440.00
21	Front Ultrasonic Sensor LH @ Grille <i>X</i>	1	\$ 440.00	\$ 440.00
Total Spare Parts				\$ 13,880.00
SPECIAL NETT				
22	Front License Plate <i>5f /</i>	1	\$ 40.00	\$ 40.00 35
Total Special Nett				\$ 40.00
LABOUR				
23	Spray Paint Front Bumper & Blending	1	\$ 300.00	\$ 300.00 200
24	Replace & Refit Affected Accident Parts	1	\$ 600.00	\$ 600.00 300
25	Remove and Refit Front Bumper Parking Sensor	1	\$ 100.00	\$ 100.00 60
26	Remove and Refit A/C Condenser Incl. A/C Gas Faciliate Repair	1	\$ 100.00	\$ 100.00 X
27	Reset Fault Code and Sync Front Parking Sensor	1	\$ 150.00	\$ 150.00 60
28	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00

ARC

Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2111-270
DATE : 17-Nov-2021
POLICY NO. : AUTO&GEN P10262698R02
VEHICLE REG. NO. : SLT8640C
VEHICLE MAKE : PEUGEOT 3008 ACTIVE PURETECH 1.2

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

Rasul
H990010068 / 13 days
22/11/21 / Resurvey after repair
W40

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
Estimate prepared by: RAYMOND TAN				
The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.				
Total Labour				\$ 1,280.00
Amount Before Excess				\$ 15,200.00
Add GST @ 7%				1,064.00
Total Amount Payable				\$ 16,264.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: