



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C


Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2111-270
DATE : 17-Nov-2021
POLICY NO. : AUTO&GEN P10262698R02
VEHICLE REG. NO. : SLT8640C
VEHICLE MAKE : PEUGEOT 3008 ACTIVE PURETECH 1.2

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR



ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Front Bumper <i>de /</i>	1	\$ 1,980.00	\$ 1,980.00
2	Front Bumper Lower <i>cut /</i>	1	\$ 380.00	\$ 380.00
3	Front Bumper Clips <i>na /</i>	10	\$ 5.00	\$ 50.00
4	Front Bumper Retainer Set <i>? cm /</i>	1	\$ 180.00	\$ 180.00
5	Front Bumper Inner Top Cover <i>cm /</i>	1	\$ 400.00	\$ 400.00
6	Front Grille Base <i>? Xan</i>	1	\$ 350.00	\$ 350.00
7	Front Grille (Center) <i>502 /</i>	1	\$ 580.00	\$ 580.00
8	Front Grille Chrome <i>cm /</i>	1	\$ 550.00	\$ 550.00
9	Front Emblem <i>na /</i>	1	\$ 180.00	\$ 180.00
10	Front Bumper Top Rubber Seal <i>X na</i>	1	\$ 280.00	\$ 280.00
11	Front Bumper Inner Bracket <i>? Xan</i>	1	\$ 400.00	\$ 400.00
12	Front Reinforcement <i>? Xan</i>	1	\$ 980.00	\$ 980.00
13	Front Sponge / Absorber <i>? Xan</i>	1	\$ 220.00	\$ 220.00
14	Front Bumper Lower Grille <i>cm /</i>	1	\$ 660.00	\$ 660.00
15	Front Bumper Lower Grille Cover <i>mis /</i>	1	\$ 580.00	\$ 580.00
16	Front Bumper Lower Extension <i>cut /</i>	1	\$ 280.00	\$ 280.00
17	Head Lamp RH <i>cm /</i>	1	\$ 2,200.00	\$ 2,200.00
18	Head Lamp LH <i>cm /</i>	1	\$ 2,200.00	\$ 2,200.00
19	Front Ultrasonic Sensor Wiring Harness <i>? Xan</i>	1	\$ 550.00	\$ 550.00
20	Front Ultrasonic Sensor RH @ Grille <i>X na</i>	1	\$ 440.00	\$ 440.00
21	Front Ultrasonic Sensor LH @ Grille <i>X na</i>	1	\$ 440.00	\$ 440.00
Total Spare Parts				\$ 13,880.00
SPECIAL NETT				
22	Front License Plate <i>54 /</i>	1	\$ 40.00	\$ 35 40.00
Total Special Nett				\$ 40.00
LABOUR				
23	Spray Paint Front Bumper & Blending	1	\$ 300.00	\$ 200 300.00
24	Replace & Refit Affected Accident Parts	1	\$ 600.00	\$ 300 600.00
25	Remove and Refit Front Bumper Parking Sensor	1	\$ 100.00	\$ 60 100.00
26	Remove and Refit A/C Condenser Incl. A/C Gas Faciliate Repair	1	\$ 100.00	\$ Xan 100.00
27	Reset Fault Code and Sync Front Parking Sensor	1	\$ 150.00	\$ 60 150.00
28	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2111-270
DATE : 17-Nov-2021
POLICY NO. : AUTO&GEN P10262698R02
VEHICLE REG. NO. : SLT8640C
VEHICLE MAKE : PEUGEOT 3008 ACTIVE PURETECH 1.2

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

Resul
Hp90010068
22/11/21
1040
13 days
Lumpsum
Resy after repair

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
Estimate prepared by: RAYMOND TAN			Total Labour	\$ 1,280.00
The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started.			Amount Before Excess	\$ 15,200.00
Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.			Add GST @ 7%	1,064.00
Quotation on parts and labour are current and subject to change.			Total Amount Payable	\$ 16,264.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

9198
35
650
9883
20%
7906.40
H/S. \$7,900