

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 30/11/2021

User ID                      PohSuan

**Section A - Accident Details**

Registration Number	SHB5336T
Case Reference Number	TAX/11/21/2015
Registration Date	26/12/2019
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	FOO HEE YONG (FU QIXIONG)
Type of Accident	Side Swipe
Accident Date and Time	10/11/2021 10:20 PM
Accident Reported Date and Time	11/11/2021 8:20 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24113037
Special Instruction to ARC, if any	TP /RIGHT REAR PORTION / NTUC - LKK
Prepared Date and Time	17/11/2021 11:44 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$600.00
Total Spray Cost	\$1,494.00	\$500.00
Total Spare Part Cost	\$6,007.64	\$1,843.44
Total Other Cost	\$700.00	\$120.00
<b>TOTAL COST</b>	<b>\$8,877.64</b>	<b>\$3,063.44 (P/P)</b>
<b>Lump Sum Total</b>	<b>\$0.00</b>	<b>\$0.00</b>
Number of Repair Days	6.0	5.0
Prepared / Adjusted By	<b>Ang Bang Kien</b>	<b>RASUL (LKK) / NTUC</b>
ARC / Surveyor Sign Off Date	<b>17/11/2021 11:59 AM</b>	<b>17/11/2021 2:51 PM</b>
Signature		
Remarks		PART BY PART REPAIR / RESUVEY BEFORE PAINT .

**Section C - Quotation and Accident Invoice Details**

<b>Quotation Number</b>	QN-2111-0401	<b>Invoice Number</b>	
<b>Quotation Date</b>	30.11.2021	<b>Invoice Date</b>	
<b>Invoice Amount</b>		<b>Prepared Date</b>	

**Section D - Details of Repair Estimates**
**Part 1 - Labour Works**

<b>Job Scope</b>	<b>Quotation from AR</b>	<b>Adjusted by Surveyor, if applicable</b>
TO REPAIR REAR PORTION RH	\$676.00	\$600.00
<b>Total Labour</b>	<b>\$676.00</b>	<b>\$600.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

<b>Job Scope</b>	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
TO RESPRAY REAR BUMPER	\$378.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY REAR DOOR RH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,494.00</b>	<b>\$500.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

<b>Job Scope</b>	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$60.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$60.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
<b>Total Other Costs</b>	<b>\$700.00</b>	<b>\$120.00</b>

**Part 4 - Spare Parts / Material Usage**

<b>Part Number</b>	<b>Portion</b>	<b>Stock Number</b>	<b>Part Name</b>	<b>Quantity</b>	<b>List Price (\$)</b>	<b>Discount (%)</b>	<b>Final Price (\$)</b>	<b>Estimator Approved</b>	<b>Surveyor Approved</b>
		52023-47030	COVER, RR BUMPER ASSY	0.00	\$332.70	0.00	\$0.00	Replace	Not Given
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace
			PIXEL STICKER	0.00	\$60.00	0.00	\$0.00	Replace	Not Given
		67003-47211	PANEL SUB-ASSY, REAR DOOR , RH	1.00	\$1,294.90	25.00	\$971.18	Replace	Replace
		68630-47050	CHECK ASSY, REAR DOOR	0.00	\$183.80	0.00	\$0.00	Replace	Not Given
		68750-20122	HINGE ASSY, REAR DOOR , UPPER RH	0.00	\$98.90	0.00	\$0.00	Replace	Not Given
		68770-52031	HINGE ASSY, REAR DOOR , LOWER RH	0.00	\$87.10	0.00	\$0.00	Replace	Not Given
		85720-47150	DOOR REAR MOTOR ASSY, POWER WINDOW	0.00	\$926.00	0.00	\$0.00	Replace	Not Given
		69803-47020	DOOR REAR WINDOW REGULATOR SUB-ASSY, RH	0.00	\$206.70	0.00	\$0.00	Replace	Not Given
		61601-47150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$871.50	25.00	\$653.63	Replace	Replace
		65637-47060	LINER, REAR FENDER , RH	0.00	\$139.80	0.00	\$0.00	Replace	Not Given
		4261147450	WHEEL, DISC	0.00	\$1,879.40	0.00	\$0.00	Replace	Not Given

X  
√  
X  
√  
X  
X  
X  
X  
X  
X  
√  
X  
X

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 30/11/2021

User ID                      PohSuan

			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given
		42602-47251	CAP SUB-ASSY, WHEEL	1.00	\$211.50	25.00	\$158.63	Replace	Replace
		43550-47020	HUB & BEARING ASSY, RH & LH	0.00	\$668.90	0.00	\$0.00	Replace	Not Given
		75850-47910	MOULDING ASSY, BODY ROCKER PANEL , RH	1.00	\$594.80	100.00	\$0.00	Replace	Repair
<b>Total</b>					<b>\$7,742.74</b>		<b>\$1,843.44</b>		

X  
✓  
X  
R

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

1,843.44  
+        600.00  
+        620.00  
-----  
3,063.44