

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63655592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 17/11/2021

User ID : TuckFoo

Section A - Accident Details

Registration Number	SHC4647Y
Case Reference Number	TAX/11/21/2026
Registration Date	12/2/2014
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	ANDREW LEE KOK KWANG
Type of Accident	Side Swipe
Accident Date and Time	11/16/2021 2:45 PM
Accident Reported Date and Time	11/16/2021 4:14 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24113036
Special Instruction to ARC, if any	TP / RIGHT REAR PORTION / NTUC - LKK
Prepared Date and Time	11/17/2021 10:44 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$300.00
Total Spray Cost	\$1,296.00	\$450.00
Total Spare Part Cost	\$4,415.24	\$407.28
Total Other Cost	\$480.00	\$100.00
TOTAL COST	\$6,867.24	\$1,257.28
Lump Sum Total	\$6,850.00	\$1,250.00
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Ang Bang Kien	Rasul
ARC / Surveyor Sign Off Date	17/11/2021 10:59 AM	17/11/2021 2:38 PM
Signature		
Remarks	LUMP SUM REPAIR / RESURVEY AFTER REPAIR PHOTO / TAIL LAMP RH DAMAGE NOT CONSISTENT.	

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/11/2021

User ID : TuckFoo

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
O REPAIR REAR PORTION RH	\$676.00	\$300.00 ✓
Total Labour	\$676.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O RESPRAY REAR BUMPER	\$378.00	\$200.00
O RESPRAY BUMPER BEAM	\$180.00	\$0.00 XAN
O RESPRAY REAR FENDER RH	\$378.00	\$200.00
O RESPRAY RIM	\$180.00	\$50.00
O RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00 XAN
Total Spray Painting & Panel Beating	\$1,296.00	\$450.00 ✓

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
O TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$40.00
O REPLACE SUNDRY PARTS	\$100.00	\$0.00 XAN
O CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00 XAN
O WASH AND VACUUM	\$60.00	\$0.00 XAN
Total Other Costs	\$480.00	\$100.00 ✓

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace ✓
		90467-07211	BUMPER CLIPS	10.00	\$2.10	25.00	\$15.75	Replace	Replace ✓
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Not Given XAN
		52016-47030	ARM SUB-ASSY. RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given XAN
		52016-47030	ARM SUB-ASSY. RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given XAN
		69997-30070	ANTENNA ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Not Given XAN
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given XAN
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given XAN
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Check ? XAN
		52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given XAN
		52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Check ? XAN
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given XAN
		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given XAN
		76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given XAN
		58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given XAN
		51442-12210	UNDER COVER RR SHIELD	0.00	\$63.90	0.00	\$0.00	Replace	Not Given XAN
		61604-47090	FENDER RR/RH	1.00	\$766.80	100.00	\$0.00	Replace	Repair R
			SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace ✓

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/11/2021

User ID : TuckFoo

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			STICKER DECAL 65558888	1.00	\$21.60	0.00	\$21.60	Replace	Replace <i>na</i>
		65637-47021	FENDER LINE RR/RH	0.00	\$141.30	0.00	\$0.00	Replace	Not Given <i>x</i>
		52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Not Given <i>x</i>
		81551-47180	TAIL LAMP RH	1.00	\$557.80	100.00	\$0.00	Replace	Old Damage <i>x</i>
		42611-47140	WHEEL DISC	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair <i>R</i>
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given <i>x</i>
		42450-47040	WHEEL HUB REAR	0.00	\$489.40	0.00	\$0.00	Replace	Not Given <i>x</i>
		75851-47900	MOULDING BODY, RH	1.00	\$673.60	100.00	\$0.00	Replace	Old Damage <i>x</i>
total					\$6,984.74		\$509.10		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
total									

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: