



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0927/2021/JT
DATE : 15-Nov-21
WIP : 53563

VEHICLE NOT IN WORKSHOP. SURVEY TBC

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TADOKORO DAI
ADDRESS : 327 BUKIT TIMAH ROAD
#06-02 FERRELL RESIDENCE
SINGAPORE 259715
TELEPHONE : HP +65 90177328
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210063244
VEHICLE NO : **SNA 5120 H**
MODEL CODE : AUDI Q3 SB 1.4 TFSI
MODEL YEAR : 25/6/2021
ENGINE NO : CZD C38056
CHASSIS NO : WAUZZZF3M1107305
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Nov-21
PLACE OF ACCIDENT : PLAZA SINGAPURA
PARKING LOT



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 5120 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI-LOCK SYSEM AND POWER MODULE WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	280 ✓
2	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY RHS FRONT DOOR.	S/N \$ 280.00	x
3	TO REMOVE AND REINSTALL FRONT SEAT ASSY. REAR SAT ASS, BACK REST, ABCD PILLAR TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N \$ 1,800.00	x
4	TO DISMANTLE AND RENEW RHS REAR DOOR. TO CUT OUT AND WELD RHS SILL PANEL AND RHS B-PILLAR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,800.00	500 ✓
5	TO RESPRAY RHS REAR DOOR, RHS REAR DOOR COVER, RHS FRONT DOOR, RHS FRONT DOOR COVER, RHS REAR WHEEL ARCH TRIMS, RHS SILL PANEL, RHS B-PILLAR AND DOOR ENTRANCE.	\$ 5,500.00	1150 ✓
6	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	x
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 13,252.00	

Door Cover x2 = 400
Arc Trim = 200
Door = 550
1150

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 5120 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR DOOR - RH <i>Dented</i>	1	\$ 2,816.00 ✓	2252.80
2	REAR DOOR OUTER SEAL - RH <i>we</i>	1	\$ 135.00 ✓	108
3	REAR DOOR CATCH - RH <i>? nn</i>	1	\$ 120.00 ?	X
4	REAR DOOR SILL PANEL - RH <i>we ne</i>	1	\$ 135.00 +	
5	REAR DOOR COVER - RH <i>Distorted</i>	1	\$ 349.00 ✓	279.20
6	REAR DOOR INNER SEAL - RH <i>2</i>	1	\$ 191.00 +	
7	REAR WINDOW REGULATOR - RH <i>3</i>	1	\$ 282.00 +	
8	REAR WINDOW REGULATOR MOTOR - RH <i>4</i>	1	\$ 271.00 +	
9	FRONT DOOR CONTROL UNIT - RH <i>5</i>	1	\$ 400.00 +	
10	FRONT SECTIONAL PART PILLAR A/B - RH <i>we ne</i>	1	\$ 3,470.00 +.	
11	SILL TRIM STRIP - RH <i>3 we ne</i>	1	\$ 556.00 +	
12	FRONT SIDE TRIM - RH <i>3</i>	1	\$ 179.00 +	
13	FRONT DOOR COVER - RH <i>6</i>	1	\$ 370.00 ✓	296
14	REAR WHEEL ARCH TRIM - RH <i>6</i>	1	\$ 536.00 ✓	428.80
15	REAR WHEEL HOUSING LINER - RH <i>we ne</i>	1	\$ 241.00 +	
16	REAR WHEEL SPOILER - RH <i>3</i>	1	\$ 40.00 +	
17	REAR ALUMINIUM RIM - RH <i>3 we ne</i>	1	\$ 1,262.00 +	
18	ACRYLIC SEALANT <i>2</i>	S/N	\$ 180.00 +	
19	CAVITY WAX <i>3</i>	S/N	\$ 140.00 +	
20	STONE CHIP <i>3</i>	S/N	\$ 180.00 +	
SUB TOTAL SPARE PARTS		:	\$ 11,853.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 5120 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	METAL FILLER POWDER <i>NE M</i>	S/N	\$ 280.00	<i>X</i>
22	SUNDRIES <i>? nec</i>	1	\$ 400.00	<i>2.56</i>
TOTAL SPARE PARTS		:	\$ 12,533.00	
TOTAL LABOUR CHARGES		:	\$ 13,252.00	
GRAND TOTAL		:	\$ 25,785.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian Lim.
SURVEYED DATE : 17/11/21.
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorized, 04 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT