

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	SOMPO INSURAN	ICE SINGAPORE PL	Ref:	CS/SMO21011765/Atf3n2		
	50 RAFFLES PLAC SINGAPORE LANI	CE #03-03 D TOWERSINGAPORE 048623	Date:	06/04/2022		
			Code:	SMO		
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMG 8251Z	Veh. Inspected	SJD 1882A		
	Policy No.		Coverage (\$)	0.00		
	Claim No.	CMTD2103394/THE	Excess (\$)	0.00		
	Assign From	MELVIN YE YONG KANG	Assign Date	18/11/2021		
2.	2. Vehicle Particulars & Condition					
	Make & Model	MAZDA 5	c.c	1998		
	Engine No.	HIDDEN	Year of Reg.	2015		
	Chassis No.	JM6CW1071F0121981	Colour	RED		
	Odometer	74940 KM	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	SPORTS RIM		
	General	GOOD				
3. Conditions of Tyres						
		Size	Make	Balance		
	R/H Front Tyre	205/55 R16	KUMHO	6 mm		
	L/H Front Tyre	205/55 R16	KUMHO	6 mm		
	R/H Rear Tyre	205/55 R16	KUMHO	6 mm		
	L/H Rear Tyre	205/55 R16	KUMHO	6 mm		
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	16/11/2021	Inspection Date	18/11/2021		
	Survey held at FLYING HIGH SPRAY PAINTING					
		BLK 1 KAKI BUKIT AVE 6 #01-29 AUTOBAY SINGAPORE 417883				
5a.	. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
	Billing		Estimate Days of Repair			
5b.	12)	Estimate l	Days of Repair			