

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892		Cust No/Name	KCV15539/TAN SENG HOE
		Reg No/Reg Date	SJF1991H / 13/03/202
		Date In/Mileage	19/11/2021/ 0
		Chassis No	GF7W0602175
		Engine No	4J11BN0171
		Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)
		Colour/Trim	P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	18/11/2021/ 11:19	BLK	282 / Kevin Leong	17687

Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	REPLACE ON FRT BUMPER CENTER GRILLE, FRT BUMPER LWR & AFFECTED AREA				900.00
	REPAIR ON FRT BUMPER PANEL				
E PNT98000	PAINT WORK ON FRT BUMPER PANEL				350.00
E PNT88000	REMOVE & REPLACE FRT PARKING ASSIST				80.00
M SUNDRY	TO SUPPLY FRT PARKING ASSIST				220.00
A 54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
M SUNDRY	TO SUPPLY FRT NUMBER PLATE WITH FRAME				50.00
M SUNDRY	SUNDRIES				30.00
M HEADLAMP ASSY,RH		1.00	1948.00	23.00	1499.96
P GARNISH,FR BUMPER,RH		2.00	48.00	23.00	73.92
M BRACKET,FR BUMPER SIDE,RH		1.00	18.00	23.00	13.86
M BRACKET,FR BUMPER SIDE,LH		1.00	18.00	23.00	13.86
M GARNISH,FR BUMPER SIDE		1.00	220.00	23.00	169.40
M GARNISH,FR BUMPER SIDE		1.00	112.00	23.00	86.24
M REINFORCEMENT,FR BUMPER		1.00	493.00	23.00	379.61
M REINFORCEMENT,FR BMRP SIDE		2.00	22.00	23.00	33.88
M FACE,FR BUMPER		1.00	851.00	23.00	655.27
M EXTENSION,FR BUMPER		1.00	517.00	23.00	398.09
M COVER,FR BUMPER		1.00	361.00	23.00	277.97
M GRILLE ASSY,RADIATOR		1.00	550.00	23.00	423.50
M COVER,FR BUMPER		1.00	25.00	23.00	19.25
M COVER,HEADLAMP SUPT PANEL		1.00	50.00	23.00	38.50

Confirm & accepted by

7% GST on	Nett 5863.31	5,863.31 410.43
-----------	-----------------	--------------------

Total Payable	6,273.74
---------------	----------

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or a cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.