

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21011767/ETY3N2**Date:** 25/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00013222001
<b>Claimant Vehicle No :</b>	PC6553B	<b>Insured Vehicle No :</b>	PC2051J
Date of Loss:	16/11/2021	Nature of Claim:	TP
		Claim No:	SNM21D206632/C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>PC6553B</b>	Engine No:	ISB67E525022235352
Make & Model:	YUTONG ZK6107HE, 6.7 D (A)	Chassis No:	LZYTBD66H1032095
Reg. Date:	07/12/2017 (Man. Year: 2017)	Odometer:	137090 km
Colour:	Multi-colour		
Engine Capacity:	6690 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	295/80R22.5	Rear Tyre Size:	295/80R22.5
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,520.00	1,305.00	7,215.00	84.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,100.00	3,050.00	5,050.00	62.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,620.00</b>	<b>4,355.00</b>	<b>12,265.00</b>	<b>73.80</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,500.00</b>		
<b>(S\$)</b>	16,620.00	3,500.00	13,120.00	78.94
<b>+ GST 7.00/7.00% (S\$)</b>	1,163.40	245.00	918.40	78.94
<b>Nett Amount (S\$)</b>	<b>17,783.40</b>	<b>3,745.00</b>	<b>14,038.40</b>	<b>78.94</b>

**INSPECTION**

Date of Assignment:	18/11/2021	
Date Inspected:	19/11/2021	Inspected At: Connect 3 ( WOODLANDS) (HQ) 566 Woodlands Road (Mandai Estate) Singapore 728697
Estimated Period of Repair:	6.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 25 May 2022)	
Parts:	N/A	YUTONG ZK6107HE 6.7 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC6553B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH SIDE COMPARTMENT COVER	Repair	1,950.00 F	*- FL
2	1		*REAR LH WHEEL COVER PANEL	Dented	1,450.00 F	*1,450.00 FL
3	1		*LH SIDE PANEL (OUTER)	Repair	4,800.00 F	*- FL
4	8		*SEALANT	Not Necessary	320.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					8,520.00	1,450.00
- List Item Discount on L Items 0.00/10.00% (\$\$)					0.00	145.00
Total Parts (\$\$)					8,520.00	1,305.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO REMOVE & REFIT RH SEATS, UPHOLSTERY, TRIMS ETC TO ASSIST REPAIR	New	600.00	0.00
2	LABOUR TO REMOVE & REFIT 6 PCS SIDE GLASSES TO ASSIST REPAIR	New	2,400.00	0.00
3	APPLY ANTI RUST	New	200.00	50.00
4	LABOUR CHARGES	New	2,100.00	800.00
5	SPRAY PAINTING WITH MULTI COLOR DESIGN	New	2,800.00	2,200.00
<b>Gross Labour Cost (\$)</b>			<b>8,100.00</b>	<b>3,050.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >