

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

G S T : 5 3 3 6 0 0 6 1 L

Ster (LKK) W/L L

19/11/21, 9.15am

L/S

M AL sy

6 dys

QT21/PC6553B/TPC

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Rd #15-02
Springleaf Tower
Singapore 079909

QUOTATION

P-1450

-10%

1305

L-3050

=4355

Dear Sir,

Cost of Repair to Vehicle PC6553B

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (\$\$)	AMOUNT (\$\$)
1.	LH side compartment cover X R	1	1,950.00	1,950.00
2.	Rear LH wheel cover panel / 00	1	1,450.00	1,450.00
3.	LH side panel (outer) X R	1	4,800.00	4,800.00
4.	Sealant	8	40.00	320.00
5.	Labour to remove & refit RH seats, upholstery, trims etc to assist repair	1	600.00	600.00
6.	Labour to remove & refit 6 pcs side glasses to assist repair	1	400.00	2,400.00
7.	Apply anti rust	1	200.00	200.00
8.	Labour charges	1	2,100.00	2,100.00
9.	Spray painting with multi color design	1	2,800.00	2,800.00
SUB-TOTAL				SS16,620.00

• Price before 7% GST

Thank you.

Yours faithfully,

Winnie Chai
HP: 9850-9666

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification to be allowed
- Supplementary cost shall be reviewed and is subject to final approval from Insurance Company

Acknowledged by Repairer

L/S-3484
=3500