

SERVICE ESTIMATE

85576 - C00001 SL: SERVICE SALES - PC

Mdm Ang Cheo Tee
BLK 427 Tampines Street 41
#08-441

Singapore 520427

Closed by : Juan Paulo Bongon Ba
Svc Consultant :
Remarks : Mdm Ang Cheo Tee

GST Reg.No: M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 18/11/2021
WIP No. . : 55443
Veh.In/Out:
*Tel.No. . : Mobile: 91455158
Reg.No. . : SLD5158H
Reg.date . : 13/05/2016
Mileage ... : 0
Chassis No: SAJAB4AG8GA925567

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRONT DOOR RH, SIDE MIRROR ASSY RH, REPAIR REAR DOOR RH	0	2500.00	0		2,500.00	S
800	TO SPRAY FRONT DOOR RH, SIDE MIRROR COVER RH, REAR DOOR RH, ETC	0	2800.00	0		2,800.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	621.00	0		621.00	S
802	TO REMOVE, REFIT & TRANSFER FR DOOR INTERIOR COMPONENTS	0	500.00	0		500.00	S
	DOOR PANEL RH <i>SE</i>	1.0 EA	1657.70			1,657.70	S
	INSULATION RH <i>re</i>	1.0 EA	189.50			189.50	S
	SEAL-DOOR RH <i>re</i>	1.0 EA	73.90			73.90	S
	SEAL-DOOR RH <i>re</i>	1.0 EA	334.60			334.60	S
	SEAL-DOOR <i>re</i>	1.0 EA	185.40			185.40	S
	SEAL-DOOR RH <i>re</i>	1.0 EA	239.40			239.40	S
	SEAL-APERTURE RH <i>re</i>	1.0 EA	192.20			192.20	S

SERVICE ESTIMATE

85576 - C00001 SL: SERVICE SALES - PC

Mdm Ang Cheo Tee
BLK 427 Tampines Street 41
#08-441

Singapore 520427

Closed by : Juan Paulo Bongon Ba
Svc Consultant :
Remarks : Mdm Ang Cheo Tee

GST Reg.No:M28920628X
0 Page 2

Inv.No. . : B&P
Inv.date. : 18/11/2021
WIP No. . : 55443
Veh.In/Out:
*Tel.No. . : Mobile: 91455158
Reg.No. . : SLD5158H
Reg.date . : 13/05/2016
Mileage ... : 0
Chassis No: SAJAB4AG8GA925567

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	CASING-DOOR PANEL R X	1.0 EA	3588.00			3,588.00	S
	DOOR PANEL CLIP XF <i>see</i>	15.0 EA	4.70			70.50	S
	FINISHER-FRAME RH ?	1.0 EA	102.10			102.10	S
	HINGE-DOOR RH UPPER X	1.0 EA	137.50			137.50	S
	HINGE-DOOR RH LOWER X	1.0 EA	132.80			132.80	S
	CHECKARM X	1.0 EA	112.70			112.70	S
	SOUND DEADENING PAD <i>see</i>	1.0 EA	578.00			578.00	S
	ADHESIVE CLEANER PN: X	1.0 EA	39.60			39.60	S
	3M07333 IMPACT RESIS X	1.0 EA	84.10			84.10	S
	3M08115 PANEL BONDIN X	1.0 EA	68.30			68.30	S
	FINISHER CHROME FRT <i>see</i>	1.0 EA	344.60			344.60	S
	DOOR FINISHER RH FRT <i>see</i>	1.0 EA	263.00			263.00	S
	REINFORCEMENT BRACKE ?	1.0 EA	113.50			113.50	S
	HANDLE-DOOR RH <i>see</i>	1.0 EA	407.30			407.30	S
	HANDLE COVER RH <i>MIS</i>	1.0 EA	48.00			48.00	S
	SEAL HANDLE COVER <i>see</i>	1.0 EA	13.10			13.10	S
	MIRROR-DOOR <i>see</i>	1.0 EA	878.60			878.60	S

SERVICE ESTIMATE

85576 - C00001
Mdm Ang Cheo Tee
BLK 427 Tampines Street 41
#08-441

SL: SERVICE SALES - PC

Singapore 520427

Closed by : Juan Paulo Bongon Ba
Svc Consultant :
Remarks : Mdm Ang Cheo Tee

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 3
Inv.date. : 18/11/2021
WIP No. . : 55443
Veh.In/Out:
*Tel.No. . : Mobile: 91455158
Reg.No. . : SLD5158H
Reg.date . : 13/05/2016
Mileage . : 0
Chassis No: SAJAB4AG8GA925567

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	MIRROR MOTOR XF XKR?	1.0 EA	276.00			276.00	S
	LAMP SIGNAL RH X	1.0 EA	168.10			168.10	S
	MIRROR GLASS RH XF X X	1.0 EA	703.70			703.70	S
	MIRROR COVER RH XF Rca	1.0 EA	185.40			185.40	S

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068
3days
19/11/21
EXCESS: 750
Repair
Resurvey before paint

Labour Total 6,421.00
Parts Total 11,187.60
Package Total 0.00

Gross Total. 17,608.60
Net..... 17,608.60
GST @ 7.0% 1,232.60
Total..... 18,841.20
Paid..... 0.00
Please Pay.. 18,841.20

GST: S=StdRated; O=OutOfScope; Z=ZeroRated