

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III21011771/TEA3Q2**Date:** 19/04/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MPC0001552\_02

**Claimant Vehicle No :** FBJ4109T **Insured Vehicle No :** SMJ6421Y

Date of Loss: 23/09/2021 Nature of Claim: TP Claim No: MPC2021D0004157

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBJ4109T**

Make & Model: YAMAHA YZF-R6, 599cc (M) Engine No: J515E031531

Reg. Date: 07/05/2014 (Man. Year: 2014) Chassis No: JYARJ155000007947

Colour: Blue Odometer: 0 km

Engine Capacity: 599 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70 R17 Rear Tyre Size: 180/70 R17

Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,496.00	9,446.40	1,049.60	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	720.00	380.00	340.00	47.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,216.00</b>	<b>9,826.40</b>	<b>1,389.60</b>	<b>12.39</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,850.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,216.00</b>	<b>7,850.00</b>	<b>3,366.00</b>	<b>30.01</b>
<b>+ Loss of Use (4.0 x S\$30.00/day) (S\$)</b>		120.00		
<b>Nett Liability (S\$)</b>		<b>7,970.00</b>		

INSPECTION

Date of Assignment: 17/11/2021

Date Inspected: 19/11/2021 Inspected At:

Pang Scooter Service (HQ)  
BLK 1006 BUKIT MERAH LANE 2 #01-06  
Singapore 159762

Estimated Period of Repair: 4.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 05 Apr 2022)	
<b>Parts:</b>	N/A	YAMAHA YZF-R6 599cc (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBJ4109T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOP CLAMP	Bent	268.00 F	*268.00 FL
2	1		*L/H HANDLE BAR	Bent	230.00 F	*230.00 FL
3	2		*FORK ASSY	Bent	3,200.00 F	*3,200.00 FL
4	1		*UNDLER BRACKET	Bent	730.00 F	*730.00 FL
5	1		*STEERING CON	Necessary	165.00 F	*165.00 FL
6	1		*FRONT WHEEL RIM	Dented	980.00 F	*980.00 FL
7	1		*L/H FRONT BRAKE DISC	Bent	320.00 F	*320.00 FL
8	1		*FRONT FENDER	Cut	285.00 F	*285.00 FL
9	1		*FRONT WHEEL SHAFT	Bent	110.00 F	*110.00 FL
10	1		*L/H FRONT FOOT REST	Cut	110.00 F	*110.00 FL
11	1		*L/H FRONT FOOT REST BRACKET	Bent	195.00 F	*195.00 FL
12	1		*GEAR SHAFT	Bent	195.00 F	*195.00 FL
13	1		*RADIATOR ASSY	Bent	780.00 F	*780.00 FL
14	1		*L/H COWLING PANEL COVER	Deformed	195.00 F	*195.00 FL
15	1		*L/H SIDE COWLING PANEL	Cracked	598.00 F	*598.00 FL
16	1		*FRONT COWLING STAY	Bent	430.00 F	*430.00 FL
17	1		*HEADLIGHT ASSY	Cut	985.00 F	*985.00 FL
18	1		*L/H BODY SLIDER	Cut	180.00 F	*180.00 FL
19	1		*L/H SLIDER BRACKET	Buckled	185.00 F	*185.00 FL
20	1		*COOLANT	Necessary	60.00 F	*60.00 FL
21	2		*FRONT WHEEL BEARING	Necessary	80.00 F	*80.00 FL
22	2		*FRONT WHEEL SEAL	Necessary	50.00 F	*50.00 FL
23	1		*IU	Cut	165.00 F	*165.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>10,496.00</b>	<b>10,496.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (S\$)</b>	0.00	1,049.60
<b>Total Parts (S\$)</b>	<b>10,496.00</b>	<b>9,446.40</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TRANSPORT	New	120.00	80.00
2	LABOUR	New	600.00	300.00
<b>Gross Labour Cost (S\$)</b>			<b>720.00</b>	<b>380.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >