

PANG SCOOTER SERVICE

Blk 1006 Bukit Merah Lane 2 #01-06 Singapore 159762

Tel : 6271 4618 Fax : 6273 2632

ESTIMATE REPAIR

BIKE NO.: FBJ 4109T

DOA: 23/09/2021

MAKE/MODEL: YAMAHA R6

S/No	DESCRIPTION	AMOUNT
1	TOP CLAMP	\$268.00 ? - bt
2	L/H HANDLER BAR	\$230.00 ? - bt
3	FORK ASSY X 2	\$3,200.00 ? - bt -
4	UNDLER BRACKET	\$730.00 ? - bt -
5	STEERING CON	\$165.00 ? ne -
6	FRONT WHEEL RIM	\$980.00 ? dd
7	L/H FRONT BRAKE DISC	\$320.00 ? - bt -
8	FRONT FENDER	\$285.00 ent -
9	FRONT WHEEL SHAFT	\$110.00 ? - bt -
10	L/H FRONT FOOT REST	\$110.00 ent -
11	L/H FRONT FOOT REST BRACKET	\$195.00 ? - bt
12	GEAR SHAFT	\$195.00 ? - bt
13	RADIATOR ASSY	\$780.00 ? - bt -
14	L/H COWLING PANEL COVER	\$195.00 de
15	L/H SIDE COWLING PANEL	\$598.00 ora -
16	FRONT COWLING STAY	\$430.00 ? - bt -
17	HEADLIGHT ASSY	\$985.00 ent -
18	L/H BODY SLIDER	\$180.00 ent -
19	L/H SLIDER BRACKET	\$185.00 buw -
20	COOLANT	\$60.00 ? ne -
21	FRONT WHEEL BEARING X 2	\$80.00 ? ne -
22	FRONT WHEEL SEAL X 2	\$50.00 ? ne -
23	TRANSPORT	\$120.00 80 -
24	LABOUR	\$600.00 300 -
25	IV	\$165.00 ent -
26	Taufik 97495749	
27	19/11/21 @ 4:15pm	
28	Resurvey after repair	
29		
30	taufik @ lkh auto. w. u.	
31	4 days.	
32		
33		
34		
35		
36		
37		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

10496
9446.40
380
9826.40
41577850
4 days