



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21011772/Uqf3n2	
			Date: 10/12/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBH 1260T		Veh. Inspected	SLR 276J
Policy No.			Coverage (\$)	0.00
Claim No.	CMTD2103406/GPL		Excess (\$)	0.00
Assign From	MELVIN YE YONG KANG		Assign Date	18/11/2021
2. Vehicle Particulars & Condition				
Make & Model	MINI COOPER (A)		c.c	1598
Engine No.	HIDDEN		Year of Reg.	2010
Chassis No.	WMWSU32090TY91042		Colour	BLACK / RED
Odometer	103129 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre		205/40 R18	PIRELLI	7 mm
L/H Front Tyre		205/40 R18	PIRELLI	7 mm
R/H Rear Tyre		205/40 R18	PIRELLI	7 mm
L/H Rear Tyre		205/40 R18	PIRELLI	7 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/11/2021		Inspection Date	18/11/2021
Survey held at	LEANG AUTOMOTIVE BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	