



TRANS EUROKARS PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



ERGO Insurance Pte. Ltd. 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 ATTN. : MOTOR CLAIMS FAX :		NAME : ADDRESS : TEL :		WIP : 47065 EXCESS : DATE: 13-Oct-21				
VEH NO :	SLK8390X	DATE IN :		CONTACT PERSON :	DEREK			
CHASSIS NO :	JM6GL1073M0454732	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM			
MODEL :	MAZDA 6	DATE REG.:	11-Aug-21	POLICY NO. :				
NATURE OF WORKS								
Parts Description								
NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	REVISED	PRICES	
1	REAR BUMPER	1			MGSK1-50-221ABB	\$ 1,099.00	\$ 1,099.00	
2	TAPE PROTECTOR	4			MBCKA-50-EM1	\$ 18.80	\$ 18.80	
3	RETAINER S.S ULTRASONIC CENTER	2			MKD45-67-UC5A51		\$ 33.60	
4	SENSOR,ULTRASONIC CENTER	2			MGMK6-67-UC1 51		\$ 378.00	
5	TAPE SEAL	2			MGSH7-50-2G1	\$ 27.40	\$ 27.40	
6	GROMMET,SCREW	4			MBHN1-50-0Z1A	\$ 10.80	\$ 10.80	
7	BRACKET CENTER REAR BUMPER	1			MDFR5-50-251		\$ 5.40	
8	REINFORCEMENT REAR	1			MGHK1-50-260		\$ 538.30	
9	COVER,UNDER-RR	1			MGSH7-50-C51		\$ 122.20	
10	RIVET	2			MTK21-50-355	\$ 18.40	\$ 18.40	
11	RIVET	6			MEA01-50-037	\$ 48.00	\$ 48.00	
12	COVER TOWING LH REAR	1			MGSH7-50-EL1 BB	\$ 46.60	\$ 46.60	
13	COVER TOWING RH REAR	1			MGSH7-50-EK1 BB	\$ 46.60	\$ 46.60	
14	RETAINER LH REAR	1			MGJR9-50-2J1		\$ 41.00	
15	RETAINER RH REAR	1			MGJR9-50-2H1		\$ 41.00	
16	GASKET TAIL LAMP RH	1			MGRF5-51-153	\$ 43.80	\$ 43.80	
17	GASKET TAIL LAMP LH	1			MGRF5-51-163	\$ 43.80	\$ 43.80	
						TOTAL PARTS	\$ 1,403.20	\$ 2,562.70
						TOTAL PARTS COST	\$ 1,403.20	\$ 2,562.70
Labour Description								
						REVISED	PRICES	
1		TO REPLACE REAR BUMPER.				\$ 660.00	\$ 1,980.00	
2		TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.				\$ 630.00	\$ 1,890.00	

3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	\$ 330.00	\$ 660.00	
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 200.00	\$ 250.00	
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 250.00	\$ 300.00	
6	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 50.00	
REMARKS: THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.			TOTAL LABOUR	\$ 2,090.00	\$ 5,130.00
			TOTAL PARTS	\$ 1,403.20	\$ 2,562.70
			TOTAL	\$ 3,493.20	\$ 7,692.70
			LESS EXCESS	\$ -	\$ -
			TOTAL AFTER EXCESS	\$ 3,493.20	\$ 7,692.70
			GST 7%	\$ 244.52	\$ 538.49
			GRAND TOTAL	\$ 3,737.72	\$ 8,231.19
REMARKS: THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.					

TRANS EUROKARS PTE LTD

 Authorised Signature