

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Estimate

Vehicle No: SLB6453J
Model and make: Honda ~~fit~~ **Jazz**
Chassis: JHMGK5850GX202392

2016

Qty Spare parts

List price

1	Rear bumper	\$	✓ 592.20	CUTV
1	Rear bumper RH side retainer	\$	26.40	48.90 } NEW
1	Rear bumper LH side retainer	\$	26.40	48.90 } NEW
1	LH rear fender	\$	✓ 629.90	DDV
1	LH rear fender glass with rubber seal	\$	✓ 182.90	NECV
1	LH rear fender inner trim board	\$	185.60	NDX
1	LH rear fender splash shield	\$	90.30	NDX
1	LH rear fender inner lower duct	\$	24.70	NDX
1	LH taillamp assy	\$	223.90	NDX
1	LH side rocker panel garnish	\$	✓ 294.50	DDV
1	LH rear door	\$	✓ 822.30	DDV
1	LH rear door frame black tape	\$	20.00	38.20 } NECV
1	LH rear sport rim	\$	350.00	693.50 } CUTV
1	LH rear shock absorber	\$	259.90	NDX
1	LH rear wheel bearing	\$	✓ 198.20	JMV
1	Rear axle beam	\$	1,205.80	NDX
1	LH front sport rim	\$	350.00	693.50 } CUTV
1	LH front shock absorber	\$	310.70	NDX
1	LH front lower arm	\$	175.80	NDX
1	LH front knuckle arm	\$	230.90	NDX
1	LH front wheel bearing	\$	✓ 126.80	JMV
1	LH front drive shaft	\$	831.40	NDX
1	LH front tie rod end	\$	72.30	NDX
1	Steering rack and pinion	\$	1,262.10	

\$ 3619.60 9,243.20
-20% \$ 723.92 1,848.64
\$ 2895.68 7,394.56

Qty Spare parts

Special Nett

1set	Rear bumper clips	\$	30.00	20.00	NECV
1	LH rear fender glass sealant	\$	30.00	60.00	NECV
1	LH rear fender glass inner seal	\$	20.00	40.00	NECV
1	LH rear fender joint sealant	\$	30.00	20.00	NECV
1	LH rear tyre	\$		280.00	NDX
1	Brake fluid	\$		55.00	NDX
1	LH side rocker panel garnish clips	\$	30.00	60.00	NECV
1	LH front tyre	\$	150.00	280.00	CUTV

290.00

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
To panel beating, cut / weld and re-align all affected panels

\$ 600.00 ~~1,000.00~~ ✓

Spray painting on affected panels

\$ 800.00 ~~1,000.00~~

Check wiring and lighting system

\$ ~~80.00~~

Apply rust coating chemical on affected panels

\$ ~~70.00~~

} NNX

Remove and replace rear inner trims, garnish, seats, roof lining and carpet to assist repair

\$ ~~320.00~~

NNX

Remove and reinstall rear bumper reverse sensors to assist repair

\$ 60.00 ~~80.00~~ ✓

Remove and reinstall LH rear fender glass to assist repair

\$ 40.00 ~~100.00~~ ✓

Remove and reinstall fuel tank, pipe, hoses and sensors to assist repair

\$ ~~180.00~~

NNX

Remove and reinstall LH rear door inner components to assist repair

\$ 80.00 ~~120.00~~

Remove and replace rear undercarriage parts to assist repair

\$ ~~450.00~~

Remove and replace front undercarriage parts to assist repair

\$ ~~400.00~~

} NDX

Conduct and adjust wheel alignment system

\$ ~~100.00~~

1580.00

Survey + Resurvey

19/11/2021

19/11/2021

1150hrs

Final amount \$

12,209.56

Parts 2895.68

SN 290.00

Labour 1580.00

4765.68

@ 20 % 953.14

3812.52

TGim

Lump Sum repair

Repair days 5

LS 3800/2

TGim

22/11/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: