

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0943/2021/JT
DATE : 19-Nov-21
WIP : 54548

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 23/11/2021
YOUR INSURED VEH NO : SBF 1680 A

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602.- Fax: 6880 4838

OWNER'S NAME : MS CHANG CHING LOU
ADDRESS : 10 LEEDON ROAD
#06-01
SINGAPORE 267833
TELEPHONE : HP +65 83899499
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7210128140
VEHICLE NO : **SNC 5366 E**
MODEL CODE : AUDI Q5 2.0 TFSI QUATTRO
MODEL YEAR : 27/10/2021
ENGINE NO : DGK 007654
CHASSIS NO : WAUZZZF1M2109721
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Nov-21
PLACE OF ACCIDENT : THE CARPARK AT 10 LEEDON
ROAD JADE MANSION

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNC 5366 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00 ✓	
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00 ✓ 500	
3	TO RESPRAY REAR UPPER BUMPER, REAR LOW BUMPER AND BOTH REAR WHEEL ARCH TRIMS.	\$ 3,000.00 ✓ 800	550 Bumper 400 ArchTrim x 2
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 4,752.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST-FOR ACCIDENT VEHICLE REGN NO. SNC 5366 E

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER - UPPER <i>Right</i>	1	\$	1,961.00	✓
2	REAR BUMPER - LOWER <i>new</i>	1	\$	1,182.00	+
3	REAR TRIM - LH / RH. <i>3 new</i>	2	\$	230.00	+
4	REAR BUMPER SPOILER <i>new</i>	1	\$	325.00	+
5	REAR BUMPER TOWING EYE - LH / RH <i>3 new</i>	2	\$	96.00	+
6	REAR BUMPER DIFFUSER	1	\$	339.00	+
7	REAR TRIM ALUMINIUM - LH / RH / CENTER <i>new</i>	3	\$	660.00	+
8	REAR TAIL LIGHT - LH / RH <i>RH cut</i>	2	\$	1,398.00	699.
9	REAR BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$	981.00	+
10	REAR BUMPER HOLING STRAP <i>not new</i>	1	\$	168.00	+
11	REAR PARKING AID SENSOR	2		TBC	+
12	REAR WHEEL ARCH TRIM COVER - LH / RH <i>new</i>	2	\$	1,166.00	✓
13	SUNDRIES <i>?</i>		\$	250.00	?
TOTAL SPARE PARTS		:	\$	8,756.00	
TOTAL LABOUR CHARGES		:	\$	4,752.00	
GRAND TOTAL		:	\$	13,508.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
SURVEYED DATE : *23/11/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT