



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

### ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV14007/THYE POH CHIN WILLIAM @JOHAN BI
	Reg No/Reg Date	SMY9439Z / 31/03/202
	Date In/Mileage	/ 9393
	Chassis No	KNAF5416MM5103060
	Engine No	G4FGLH712926
	Make/Model	KIA/CERATO 1.6 A GT LINE H370
	Colour/Trim	KLK STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	18/11/2021/ 16:51	BLE	261 / Edwin Caina	42700			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2000.00
RENEW FR BUMPER , BONNET & FR SUPPORT PNL					2 X 490			809
REPAIR LHF FENDER								1050.00
E PNT98000								100.00
RESPRAY FR BUMPER , BONNET & LHF FENDER					3 X 350			7
E PNT88000								80.00
REMOVE & REFIT AC COND & RADIATOR								30.00
M SUNDRY								120.00
TOP UP AC GAS								50.00
A 54900099								40.00
CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM								60.00
A 10028901								20.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								1768.00
M SUNDRY								1201.60
SUPPLY FR NUMBER PLATE WITH CASING								10.40
M SUNDRY								506.40
APPLY ANTI CORROSION ON AFFECTED AREAS								388.00
M SUNDRY								262.40
SUPPLY BODY PNL SEALANT								30.40
M SUNDRY								172.80
Sundries								114.40
M LAMP ASSY-HEAD,LH					1.00	2210.00	20.00	11.20
M PANEL ASSY-HOOD					1.00	1502.00	20.00	67.20
M CLIP-HOOD INSULATING PAD MTG					13.00	1.00	20.00	91.20
M COVER-FR BUMPER					1.00	633.00	20.00	
M GRILLE-FRONT BUMPER					1.00	485.00	20.00	
M GRILLE ASSY-RADIATOR					1.00	328.00	20.00	
M GARNISH-RADIATOR GRILLE					1.00	38.00	20.00	
M MOULDING-FRONT BUMPER,LH					1.00	216.00	20.00	
M LAMP ASSY-SIDE REPEATER,LH					1.00	143.00	20.00	
M AIR DUCT-FR BUMPER,LH					1.00	14.00	20.00	
M ABSORBER-FRONT BUMPER ENERGY					1.00	84.00	20.00	
M STIFFNER-FR BPR LWR					1.00	114.00	20.00	

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd.	Cust No/Name	LCV14007/THYE POH CHIN WILLIAM @JOHAN BI
MOTOR CLAIM DEPARTMENT	Reg No/Reg Date	SMY9439Z / 31/03/202
78 SHENTON WAY #09-16	Date In/Mileage	/ 9393
AIG BUILDING	Chassis No	KNAF5416MM5103060
SINGAPORE 079120	Engine No	G4FGLH712926
Contact No 64191000	Make/Model	KIA/CERATO 1.6 A GT LINE H370
	Colour/Trim	KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	18/11/2021/ 16:51	BLE	261 / Edwin Caina	42700			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BRACKET-FR BUMPER UPR SIDE MTG					1.00	22.00	20.00	17.60
M WIRING ASSY-BUMPER EXTENSION					1.00	207.00	20.00	165.60
M ULTRASONIC SENSOR ASSY-P.A.S					2.00	163.00	20.00	260.80
M BEAM COMPLETE-FR BUMPER					1.00	497.00	20.00	397.60
M CARRIER ASSY-FRONT END MODULE					1.00	675.00	20.00	540.00

# Estimate

Steve (CLKK)

SURVEYOR NAME: \_\_\_\_\_

SURVEYOR SIGNATURE: \_\_\_\_\_

DATE: \_\_\_\_\_

REMARKS: \_\_\_\_\_

5 days

19/11/21, 11.00a  
OD M AL  
EXCER - ?

P/P

My Bill

Confirm &amp; accepted by

LKKA Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts selection - subject to resurvey

Authorized signatory and company stamp

	Nett	9,555.60
7% GST on	9555.60	668.89
<b>Total Payable</b>		<b>10,224.49</b>

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.