

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 68467483

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0404/21

DATE : 16-NOV-2021

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

S(079909)

TEL : 63896111

FAX : 62247175

OWNER'S NAME : A'ZONE CORPORATION PTE LTD

ADDRESS : 14 LOYANG DRIVE

S(508941)

TELEPHONE NO : 65454800/97220103

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM

POLICY NO : 2100407534-06

VEHICLE NO : SKS1844U

MODEL CODE : BDUARGAN17EWA-----E4

MODEL/YEAR : NISSAN ALMERA 1.5L AT COMFORT EURO4

ENGINE NO : HR15972109C

CHASSIS NO : MNTBBAN17Z0500063

MILEAGE : 80959 KM

DATE IN : 16/11/2021

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : ELMER

ACCIDENT DATE : 16/11/2021

- 9645 0084 elmy@tanchong.com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKS1844U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR TRUNKFLOOR & TRUNKLID RENEW RR END PANEL AND REAR BUMPER	1400.00	
2	ZZ/002	CHARGES TO SPRAY PAINTING TRUNKFLOOR,RR END PANEL TRUNKLID AND REAR BUMPER	1250.00	
3	ZZ/003	RENEW REVERSE SENSOR	110.00	
4	ZZ/004	REMOVE AND INSTALL BOTH RR COMB LAMP AND CHECK WIRING SYSTEM	48.00	
5	ZZ/005	APPLY SEALANT TO REAR END PANEL	100.00	
6	ZZ/006	COMPLETE VEHICLE POLISHING	180.00	
7	ZZ/007	COMPUTER CHECK DIAGNOSIS	120.00	
8	ZZ/008	REMOVE AND INTALL BOTH INNER TRIM RR FENDER	240.00	
		TOTAL LABOUR CHARGES	3448.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKS1844U

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	SUNDRIES	NPN			100.00
2	SENSOR-REVERSE	SENSOR			250.00
3	EMBLEM T/LID ALMERA	84895-3BB0A	59.90		
4	EMBLEM REAR NISSAN	84890-3AA0A	59.90		
5	REAR END PANEL	G9110-3BGMA	434.90		
6	STAY RR BUMPER @ SGD\$96.90 EACH	H5212-1HMMA	193.80		
7	ENERGY ABSORBER RR BUMPER	85090-7W80A	141.40		
8	LH SIDE BRACKET RR BUMPER	85220-3BG0A	42.50		
9	RH SIDE BRACKET RR BUMPER	85221-3BG0A	42.50		
10	CLIP RR BUMPER @ SGD \$1.30 EACH	01553-10501	13.00		
11	REAR BUMPER	85022-7W83H	561.40		
12	REAR LICENCE PLATE	RLP			60.00
SUB TOTAL			1549.30	0.00	410.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			309.86	0.00	0.00
GRAND TOTAL			1239.44	0.00	410.00
OVERALL TOTAL			1649.44		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKS1844U

TOTAL LABOUR CHARGES 3448.00
TOTAL SPARE PARTS CHARGES 1649.44

GRAND TOTAL 5097.44 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the
 affected vehicle. Should we require further labour
 charges & spare parts in the process of repairs, we
 shall inform you accordingly.