

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SLN8164S. 2017 May

Mazda 3 1496cc

JM6BN22A8H0146618

TP AXA.
Denise.

Front Bumper	Distorted.	1125.50 ✓
Front Bumper Clips.	New	30(SN) ✓
Front Bumper Side Holder LH.	Dented	45.20 ✓
Front Bumper Reinforcement.	Dented	590.10 ✓
Front Bumper Fog Lamp LH.	New	465.80 X
Front Bumper Fog Lamp Cover LH.	Wt	92.90 ✓
Front Bumper Fog Lamp Bracket.	cracked	69.40 ✓
Front Bumper Lamp LH.	cracked	312 ✓
Front Bumper Lower Spoiler	Dehnd	1000(SN) 850(SN) ✓
Front Bumper Top Cover	Dehnd	285.80 ✓
Front Bumper Lower Grille	New	124.20 X
Front Bumper Lower Grille Side Cover LH.	Missing	35.10 ✓

SLN 8164S.

Front Bumper Bracket LH.	cracked	30.40	/
Front Bumper Inner Garnish.	Del'd	149.40	✓
Front Grille	cracked	589	/
Front Grille clips.	m	20(SN)	✓
Front Grille Logo.	m	71	✓
Front Grille Top Cover	lt	91.40	/
Front Grille Top Cover clips.	m	20(SN)	✓
Front Grille Lower Bracket.	Best	85.90	/
Front Grille Side Moulding	LT x02	176.70	176.70
Front Support Panel.	cracked	569.70	/
Air Con Condenser	2	1019	X
Radiator	1	1118.50	X
Radiator Top Panel.	Buckled	457	/
Headlamp LH.	smashed	3871	/
Headlamp Panel LH.	Distorted	208.10	✓

SLN 81645.

Bonnet	Distorted	106.7	✓
Bonnet lock	Jammed	197.10	✓
Bonnet Hinge x 02	Bent	81 x 2 = 162	✓
Bonnet Weatherstripe	ut	60.80	✓
Front LH Fender	Distorted	417.50	✓
Front LH Fender Bracket.	Bent	58.20	✓
Front LH Fender Inner Shield.	torn	185.50	✓
Front LH Fender Inner Shield lips.	m	30 (sw).	✓
Front LH Wheel Rim.	} NP NEC	850 (sw)	+
Front LH Tyre.		300 (sw).	+
Front LH Lower Arm.		485.40	+
Front LH Knuckle Arm.		564.20	+
Front LH Shock Absorbers		298	+

SLN 8164 S.

Front LH Wheel Hub & Bearing ^M 325.40. x

Stop Start Motor Cladded 3890.40. /

Mer 50(SN). /

Coolant.

114984.10

114987.28

SN: 1000

Labour: 2890

total: 15877.28

H/s: RTK. 08 Days

~~1800~~ 1300

~~1400~~ 1200

~~100~~ 30

~~100~~ 60

~~100~~ 60

~~150~~ 60

350 x

150 x

~~200~~ 120

60. ✓

Panel Beating

Spray Painting,

Wiring.

To remove condenser and to }
top up air con gas }

To remove radiator and to }
top up coolant }

To spray tuft coat
To remove front undercarriage

To perform wheel alignment.

To perform diagnostic test.

lowing charges.