

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMR8853D**LAD2111-007**

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

SMR8853D

JTDKB3FU103091051

TOYOTA

PRIUS GEN 4

05/11/2021

CHINA

30/01/2020

| | PART |
|---|--|
| 1 | COVER, FRONT BUMPER <i>/ Re</i> |
| 1 | REINFORCEMENT SUB-ASSY, FRONT BUMPER ? |
| 1 | ABSORBER, FRONT BUMPER ENERGY ? |
| 1 | BRACKET, FRONT BUMPER SIDE, RH <i>X NN</i> |
| 1 | UNIT ASSY, HEADLAMP, RH ? |
| 1 | GRILLE SUB-ASSY, RADIATOR ? |
| 1 | GRILLE, RADIATOR, LOWER NO.1 ? |
| 1 | EMBLEM ASSY, RADIATOR GRILLE <i>/ MCL</i> |

| | LIST |
|----|----------|
| \$ | 521.00 |
| \$ | 716.60 |
| \$ | 80.20 |
| \$ | 59.30 |
| \$ | 2,637.60 |
| \$ | 422.50 |
| \$ | 178.60 |
| \$ | 105.80 |

| | |
|--------------|--------------------|
| TOTAL | \$ 4,721.60 |
| 25% | \$ 1,180.40 |
| | \$ 3,541.20 |

| | Special Nett |
|--------------|--|
| 1 | FRT BUMPER CLIP <i>/ MCL</i> |
| 1 | FR NUMBER PLATE WITH MOULDING <i>/ BT.</i> |
| TOTAL | |

| | |
|-----------|---------------|
| \$ | 60.00 |
| \$ | 200.00 |
| \$ | 260.00 |

TOTAL PARTS \$ 3,801.20**LABOUR**

| | | | |
|---|----|--------|----------|
| To Rust-Proofing and apply undercoat Of The Affected Areas. | \$ | 240.00 | <i>X</i> |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. | \$ | 380.00 | <i>X</i> |

San

Trans-cab Auto Services Pte Ltd

LAD2111-007

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMR8853D

Panel Beating, Knocking And Straightening The Necessary
Portion, Remove And Renewal Of Parts, Adjust And Realign
The Same

\$ 1,600.00 *200*

To transfer of rear end panel fittings, attachment to facilitate
bodywork repair.

\$ 380.00 *X nn*

Putty And Spray Painting Of The Affected Portion.

\$ 1,600.00 *200*

To reinstall rear bumper parking sensor.

\$ 170.00 *X*

To transfer of tire, rim and on wheel balancing.

\$ 170.00 *X*

To Check Electrical Lighting Concerned.

\$ 170.00 *X*

To check steering geometry and computer wheel alignment

\$ 220.00 *X*

To remove and refit of rear fender fittings, attachment and

\$ 170.00 *X***TOTAL \$ 5,100.00****Over All Total \$ 8,901.20****(PART-BY-PART) Repair Days****20 days**

*2 Days
Lumpsum repair
After repair photos.
Gino Riccio - 82880282
17/11/21*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: