



FALCON-AIR

LIM CHUAN HONG KATHERINE
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721
DAVID ANG - 81265210

Attention : Motor Claim Department

Contact : 94370770

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

Not Notified
L1 Day & 6600h
Repair After Paint

9 days

Estimate : ES012287

Date : 18/11/2021
Vehicle Num. : SMV 4054Z
Make/Model : HONDA VEZEL 1.5X CVT-2016
Chassis/Eng# : RU11204556
Accident Date : 18/11/2021
Claim No. : CMTD2103417/GPL
Reference : TP - NTUC AGT SOMPO (SM)
Policy No. : 5120724508

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

		LIST ITEMS : 953
1.	1 PC	TAILGATE
2.	1 PC	TAILGATE LOCK
3.	1 PC	TAILGATE EMBLEM (VEZEL)
4.	1 PC	TAILGATE WEATHERSTRIP
5.	1 PC	TAILGATE GLASS MOULDING
6.	2 PCS	TAILGATE LAMP
7.	1 PC	TAILGATE TRIM BOARD
8.	1 PC	REAR END PANEL
9.	1 PC	REAR END PANEL TOP GARNISH
10.	1 PC	SPARE TYRE PANEL
11.	1 PC	SPARE TYRE PANEL REINFORCEMENT
12.	1 PC	SPARE TYRE PANEL UNDERCOVER
13.	1 PC	REAR BUMPER
14.	1 PC	LH REAR BUMPER REFLECTOR
15.	1 PC	LH REAR BUMPER
16.	1 PC	REAR EXHAUST
17.	1 PC	LH REAR FENDER ARCH GARNISH
18.	2 PCS	TAILLAMP
19.	1 PC	LH REAR FENDER INNER TRIM
20.	1 PC	BUZZER SENSOR

List TotalS\$:

20.00% Discount S\$:

B1	1,050.00	✓
DL	256.00	✓
90.50SN	40.00	✓
AT	181.00	506h
DL	118.00	✓
CV	459.40	✓
B1	918.80	✓
B1	193.40	✓
B1	453.40	✓
DL	92.30	✓
B1	818.60	2
DL	258.00	8
DL	127.70	✓
B1	553.10	✓
DL	148.00	X
B1	212.80	X
B1	527.40	2
B1	190.30	✓
488.30	976.60	✓
DL	350.70	X
CMT	105.20	✓
		7,571.30
		1,514.26
		6,057.04

CONTINUE / ...

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
; Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

ASSIGNMENT

Veh No:

SMV 4054Z Yr Regn: 12 16

M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /



FALCON-AIR

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D Page 2 / 2
GST Reg. No.: 199501140D

LIM CHUAN HONG KATHERINE
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721
DAVID ANG - 81265210

Attention : Motor Claim Department

Contact : 94370770

Estimate : ES012287

Date : 18/11/2021

Vehicle Num. : SMV 4054Z

Make/Model : HONDA VEZEL 1.5X CVT-2016

Chassis/Eng# : RU11204556

Accident Date : 18/11/2021

Claim No. : CMTD2103417/GPL

Reference : TP - NTUC AGT SOMPO (SM)

Policy No. : 5120724508

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1 SET
1 PC
10 PCS

SPECIAL NETT ITEMS :
REVERSE SENSOR
SEALANT
REAR BUMPER CLIP

Nett	200.00
Nett	40.00
2.00 Net	20.00
Special Nett Total S\$:	310.00

LABOUR :

TO TRANSFER DOOR MECHANISM
TO REMOVE/REFIX REAR WINDSCREEN GLASS
TO REMOVE/REFIT REVERSE SENSOR INTO NEW BUMPER
TO RUSTPROOF ACCIDENT DAMAGE AREA AND WATER
TO REMOVE/REPLACE EXHAUST
TO CUT-OUT/RE-WELD REAR END PANEL, SPARE TYRE PANEL,
STRAIGHTEN REAR CHASSIS INCLUDING REPLACEMENT OF PARTS
TO SPRAY PAINT ON TAILGATE, LH CORNER REAR BUMPER, REAR
END PANEL, SPARE TYRE PANEL, FLOOR BOARD PANEL

60.00
100.00
120.00
50.00
150.00
150.00
1,400.00
1,000.00
2,970.00

Labour Total S\$:

E. & O.E.

Total S\$: 9,337.04

FALCON AIR AUTO SERVICES PTE LTD

Estimation was prepared from visual inspection. Further materials and labour charges may be required when repairs are carried out. We will advise you accordingly.

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg