



FALCON-AIR

LIM CHUAN HONG KATHERINE
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721
DAVID ANG - 81265210

Attention : Motor Claim Department

Contact : 94370770

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

Not Not heited
1/1 Day &
Repair After Paint

9 days

Estimate : ES012287

Date : 18/11/2021
Vehicle Num. : SMV 4054Z
Make/Model : HONDA VEZEL 1.5X CVT-2016
Chassis/Eng# : RU11204556
Accident Date : 18/11/2021
Claim No. : CMTD2103417/GPL
Reference : TP - NTUC AGT SOMPO (SM)
Policy No. : 5120724508

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

		LIST ITEMS :
1.	1 PC	TAILGATE
2.	1 PC	TAILGATE LOCK
3.	1 PC	TAILGATE EMBLEM (VEZEL)
4.	1 PC	TAILGATE WEATHERSTRIP
5.	1 PC	TAILGATE GLASS MOULDING
6.	2 PCS	TAILGATE LAMP
7.	1 PC	TAILGATE TRIM BOARD
8.	1 PC	REAR END PANEL
9.	1 PC	REAR END PANEL TOP GARNISH
10.	1 PC	SPARE TYRE PANEL
11.	1 PC	SPARE TYRE PANEL REINFORCEMENT
12.	1 PC	SPARE TYRE PANEL UNDERCOVER
13.	1 PC	REAR BUMPER
14.	1 PC	LH REAR BUMPER REFLECTOR
15.	1 PC	LH REAR BUMPER
16.	1 PC	REAR EXHAUST
17.	1 PC	LH REAR FENDER ARCH GARNISH
18.	2 PCS	TAILLAMP
19.	1 PC	LH REAR FENDER INNER TRIM
20.	1 PC	BUZZER SENSOR

List TotalS\$:

20.00% Discount S\$:

B1	1,050.00	✓
B1	256.00	✓
B1	40.00	✓
CVT	181.00	soln
B1	118.00	✓
CVT	459.40	✓
B1	918.80	✓
B1	193.40	✓
B1	453.40	✓
B1	92.30	✓
B1	818.60	✓
D17	258.00	✓
D17	127.70	✓
B1	553.10	✓
B1	148.00	X
B1	212.80	✓
B1	527.40	✓
B1	190.30	✓
488.30	976.60	✓
CVT	350.70	✓
CVT	105.20	✓
		7,571.30
		1,514.26
		6,057.04

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON - AIR AUTO SERVICES PTE LTD



Attention : Motor Claim Department
Contact : 94370770

Date : 18/11/2021
Vehicle Num. : SMV 4054Z
Make/Model : HONDA VEZEL 1.5X CVT-2016
Chassis/Eng#: RU11204556
Accident Date : 18/11/2021
Claim No. : CMTD2103417/GPL
Reference : TP - NTUC AGT SOMPO (SM)
Policy No. : 5120724508

S/N	Quantity	Particular	Unit Price	Amount S\$
SPECIAL NETT ITEMS :				
1.	1 SET	REVERSE SENSOR	250.00	250.00
2.	1 PC	SEALANT	40.00	40.00
3.	10 PCS	REAR BUMPER CLIP	2.00	20.00
Special Nett Total S\$:				310.00
LABOUR :				
TO TRANSFER DOOR MECHANISM			100.00	100.00
TO REMOVE/REFIX REAR WINDSCREEN GLASS			120.00	120.00
TO REMOVE/REFIT REVERSE SENSOR INTO NEW BUMPER			50.00	50.00
TO RUSTPROOF ACCIDENT DAMAGE AREA AND WATER			150.00	150.00
TO REMOVE/REPLACE EXHAUST			150.00	150.00
TO CUT-OUT/RE-WELD REAR END PANEL, SPARE TYRE PANEL,				
STRAIGHTEN REAR CHASSIS INCLUDING REPLACEMENT OF PARTS				
TO SPRAY PAINT ON TAILGATE, LH CORNER REAR BUMPER, REAR				
END PANEL, SPARE TYRE PANEL, FLOOR BOARD PANEL			1,400.00	1,400.00
Labour Total S\$:			1,000.00	2,970.00
E. & O.E.			Total S\$:	9,337.04

for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.