

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI21011804/UTY3E2

**Date:** 22/03/2022

### REFERENCE

Insured/Claimant: GIRI JODHAV Policy No: DMPCSNW00097532109  
Date of Loss: 12/11/2021 Nature of Claim: OD Claim No: SNM21D206539/C01/TANKW

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJX5914K**  
Make & Model: BMW 523I, 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A) Engine No: 04657391N52B25AF  
Reg. Date: 28/06/2010 (Man. Year: 2010) Chassis No: WBAFP32030C543925  
Colour: Black Odometer: 82411 km  
Engine Capacity: 2497 cc  
Market Value/New Car Price: S\$30,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 225/55R17 Rear Tyre Size: 225/55R17  
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	31,000.30	19,766.30	11,234.00	36.24
Miscellaneous Items	505.00	265.00	240.00	47.52
Labour	2,513.00	1,491.01	1,021.99	40.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>34,018.30</b>	<b>21,522.31</b>	<b>12,495.99</b>	<b>36.73</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>17,000.00</b>		
<b>(S\$)</b>	34,018.30	17,000.00	17,018.30	50.03
<b>+ GST 7.00/7.00% (S\$)</b>	2,381.28	1,190.00	1,191.28	50.03
<b>Nett Amount (S\$)</b>	<b>36,399.58</b>	<b>18,190.00</b>	<b>18,209.58</b>	<b>50.03</b>

### INSPECTION

Date of Assignment: 19/11/2021 Present Location: Car City Auto Centre Pte Ltd (HQ)  
Date Inspected: 19/11/2021 Inspected At: Car City Auto Centre Pte Ltd (HQ)  
Estimated Period of Repair: 7.0 days Blk 9006 #01-198, Tampines Street 93  
Singapore 528840

**Adjuster:** MARCUS CHUA

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 22 Mar 2022)

**Parts:** 143 BMW 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SJX5914K)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		<b>*PARTS</b>		30,565.30 F	*19,331.30 F	
<b><u>Supplementary #1</u></b>							
2	1		<b>*thermostat housing assy</b>	Cracked	200.00 F	*200.00 F	
3	1		<b>*v-belt</b>	Cut	85.00 F	*85.00 F	
4	1		<b>*front water hose</b>	Torn	120.00 F	*120.00 F	
5	1		<b>*front headlight RH seal</b>	Torn	30.00 F	*30.00 F	
					<b>Total Parts (S\$)</b>	<b>31,000.30</b>	<b>19,766.30</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	EXTRAS	505.00	265.00
			<b>Sub Total (\$\$)</b>	<b>265.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	1,599.50	644.00
2	SPRAY PAINTING	New	913.50	847.01
			<b>Gross Labour Cost (\$\$)</b>	<b>1,491.01</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >