

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Friday, 10 December 2021 3:43 PM  
**To:** shushi.tang@vw.com.sg  
**Cc:** Cheong, Pearlyn (VWG Singapore); Wong, Meiy (VWG Singapore); SUR  
**Subject:** RE: FCI-OD SLS 5286S DOA: 18/11/2021  
**Attachments:** SLS5286S SUPPLEMENTARY.pdf

Dear Shu Shi,

Kindly proceed the supplementary as attached with our surveyor marking.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>  
**Sent:** Monday, 22 November 2021 2:43 PM  
**To:** shushi.tang@vw.com.sg  
**Cc:** Cheong, Pearlyn (VWG Singapore) <Pearlyn.cheong@vw.com.sg>; Wong, Meiy (VWG Singapore) <meiy.wong@vw.com.sg>; SUR <sur@lkkauto.com>  
**Subject:** FCI-OD SLS 5286S DOA: 18/11/2021

Dear Shu Shi,

As instructed by our client, please proceed to repair the insured vehicle **SLS 5286S (Excess \$750/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their rights not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)