

SIN FATT DIESEL MOTOR

8 KAKI BUKIT AVE 4 #05-25 PREMIER @ KB SINGAPORE 415875

ONG CONCRETE CONTRACTOR P/L
BLOCK 3020A UBI ROAD 1
01-33
Singapore 408714

22nd NOV 2021

TP SMPT.
Hui Zhen

Accident date: 06th NOV 2021

Estimated repair cost for vehicle no: GBH3013C OPEL COMBO 1.6 ' 2018

S/n	Qty	Items	U/price	Amount
1	1	rear tyre -RH		\$350.00 X
2	1	Rear rim -RH		\$400.00 X
3	1	rear shock absorber-RH		\$325.00 X
4	1	Rear lower arm-RH		\$255.00 X
5	1	Rear wheel bearing-RH		\$158.00 X
6	1	Rear fender -RH		\$951.00 X
7	1	Front door-RH <i>Dented</i>		\$1,150.20 X
8	1	Front door handle -outer -RH <i>new</i>		\$125.00 X
9	1	Front door lower protector -RH <i>ut</i>		\$215.00 X
10	1	front door inner lock -RH <i>new</i>		\$185.20 X
11	1	Rear door inner rubber-RH <i>new</i>		\$165.20 X
12	4	Rear door -RH <i>Dented</i>		\$1,150.00 X
13	1	Rear door handle outer -RH <i>new</i>		\$125.00 X
14	1	Rear R/H door rubber <i>new</i>		\$85.00 X
15	1	Rear door lower protector -RH <i>ut</i>		\$215.00 X
16	1	Rear door inner lock -RH <i>new</i>		\$185.20 X
17	1	rear door logo -RH <i>new</i>		\$50.00 30(SW)

2980.40.
2682.36

Subtotal :- \$6,089.80

Labour charges

To remove & refix rear undercarriage

\$180.00 X

To Check Wiring System

\$60.00 30

Tuff Kote

1380

\$120.00 50

Wheel alignment (computer)

\$120.00 X

Panel beating

\$800.00 500

Spray painting

\$800.00 ✓

Subtotal :- \$2,080.00

Total:- \$8,169.80

Total: 4092.36

1/51 3.2K.

04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer