

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TF 3042/11/21

Your Ref:

Date: 19th NOV 2021

M/S MITSUBISHI HC CAPITAL ASIA PACIFIC PTE. LTD.
111, Somerset Rd, #14-05, Singapore 238164

Estimate cost of repair to TOYOTA HARRIER PREMIUM 2.0 CVT SUV - SLS 6773 X

1 pc tail gate door	1,369.50	✓
1 pc tail gate door 'HARRIER' emblems	62.20	✓
1 pc tail gate door logo emblems	52.20	✓
1 pc tail gate door logo base garnish	1,220.20	✓
8 pcs tail gate door logo base garnish clips	38.40	✓
16 pcs tail gate door inner trim board clips	83.20	✓
2 pcs tail gate door o/s & n/s hinge	248.80	✓
2 pcs tail gate door o/s & n/s shock absorber (E)	1,793.20	✓
1 pc tail gate lock	763.30	✓
1 pc tail gate lock cover	42.20	✓
1 pc tail gate lock stricker	52.20	✓
1 pc tail gate lock key less sensor	147.90	✓
2 pcs tail gate door o/s & n/s reflector	824.40	✓
1 pc tail gate door weatherstrip	410.40	✓
1 pc antenna sensor (rear bumper inner)	144.20	✓
2 pcs tail gate side door o/s & n/s rubber sensor	2,074.40	✓
1 set rear windscreen glass outer moulding	159.00	✓
1 pc rear windscreen glass inner dam seal	55.00	✓
1 pc rear windscreen glass sealant	60.00	✓
1 pc rear number plate & frame	60.00	✓
2 pcs o/s & n/s tail lamp assy	1,110.20	✓
2 pcs o/s & n/s tail lamp clips stopper	13.60	✓
16 pcs rear o/s & n/s fender inner garnish clips	83.20	✓
1 pc rear bumper	1,395.30	✓
10 pcs rear bumper clips	43.00	✓
2 pcs rear bumper o/s & n/s screw stopper	16.40	✓
1 pc rear bumper sponge damper	137.80	✓
2 pcs rear bumper o/s & n/s stay bracket	367.40	✓
2 pcs rear bumper o/s & n/s side retainer	181.60	✓
2 pcs rear bumper o/s & n/s top retainer	189.60	✓
1 set rear bumper reverse sensor	320.00	✓
1 pc rear bumper lower garnish	466.10	✓
8 pcs rear bumper lower garnish clips	34.40	✓
2 pcs rear bumper lower garnish o/s & n/s reflector	108.20	✓
1 pc rear end panel	715.50	✓
1 pc rear end panel top garnish (with chrome)	599.20	✓
6 pcs rear end panel top garnish clips	37.20	✓
1 pc rear centre floor board cover	652.90	✓
1 pc rear centre tool box board	711.20	✓
1 pc rear o/s floor board cover	358.80	✓
1 pc rear n/s floor board cover	358.80	✓
1 pc rear o/s tool box board	492.20	✓
1 pc rear n/s tool box board	492.20	✓
1 pc rear floor board panel	973.20	✓
1 pc rear floor board panel sealant	75.00	✓
1 pc rear floor board panel insulator	546.60	✓
1 pc rear top spoiler seal	55.00	✓
1 pc rear top spoiler sealant	60.00	✓

\$ 20,255.30 10667.16

Balance C/F.....

11765.32

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3042/11/21 Your Ref: _____ Date: 23rd NOV 2021

M/S MITSUBISHI HC CAPITAL ASIA PACIFIC PTE. LTD.
111, Somerset Rd, #14-05
Singapore 238164

SUPPLEMENTARY BILL For TOYOTA HARRIER SUV 2.0 (A) - SLS 6773 X

1 pc floor board panel spare tyre cushion sponge damper	285.20
1 pc rear n/s fender airscoop grille	172.90
1 pc rear n/s fender stopper	25.20

Less 25% \$ 484.30
\$ 121.08

\$ 363.22
=====

Dollars : Three Hundred Sixty Three And Cents Twenty Two Only.

HUP MOTOR TRADING & SERVICE



合 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3042/11/21

Your Ref:

Date: 19th NOV 2021

M/S MITSUBISHI HC CAPITAL ASIA PACIFIC PTE. LTD.,

Balance B/P.... \$ 20,255.30 10667.16

Less 25% \$ 5,063.83

\$ 15,191.47 8000.37

To remove & refix affected wiring system, including wiring check up for reverse camera, third brake light, sensor & necessary parts, including re-set rear shock absorber.

180.00 60

To remove & refix rear windscreen glass & necessary parts.

150.00 120

To transfer tail gate door inner trim board cover, hinge, shock absorber, wiper motor, arm, inner lock, third brake light, garnish, spoiler & necessary parts into new door.

280.00 100

To remove & refix floor mat, garnish, tool set board, floor board cover, spare tyre, cushion seat & necessary parts.

180.00 80

To remove, refix & pump sealant for tail gate door top spoiler & necessary parts.

150.00 40

To respray Tuff-Kote on all affected accident parts.

160.00 80

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear floor board panel, rear o/s & n/s fender, tail lamp panel & necessary parts, to weld, renew & align above parts.

1,850.00 1200

To putty & respray painting on all affected accident parts.

2,000.00 1500

\$ 20,141.47 2600

Dollars : Twenty Thousand One Hundred Forty One And Cents Forty Seven Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6 Days - 10 Days

P/P

before paint photos

Gmo Qiang - 82880282

Gmo Qiang @ LKK auto. com

22/11/21.

10841.65

P-12177-28
252

P-9132-96

S.N 180

2-3180

1249296