



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2205079
3 ANSON ROAD #16-00	INV Date	17/08/2022
SPRINGLEAF TOWER	Reference	CC6/CTI21011825/Ega3q2
SINGAPORE 079909	Code	CTI

### PROFESSIONAL SERVICE FEE

Vehicle No.	SMF 3738A
Insured Veh.	SKS 9790M
Claim No.	SNM21D206706
Policy No.	DMCVSNA00003052101
Accident Date	16/11/2021
Inspection Date	22/11/2021

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC6/CTI21011825/Ega3q2 Date: 17/08/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKS 9790M	Veh. Inspected	SMF 3738A
Policy No.	DMCVSNA00003052101	Coverage (\$)	0.00
Claim No.	SNM21D206706	Excess (\$)	0.00
Assign From		Assign Date	22/11/2021
2. Vehicle Particulars & Condition			
Make & Model	HONDA JAZZ	c.c	1318
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JHMGK3850JX227153	Colour	BROWN
Odometer	26999 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175/55 R15	DUNLOP	4 mm
L/H Front Tyre	175/55 R15	DUNLOP	4 mm
R/H Rear Tyre	175/55 R15	DUNLOP	4 mm
L/H Rear Tyre	175/55 R15	DUNLOP	4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/11/2021	Inspection Date	22/11/2021
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 3738A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	CRUSHED	880.00	492.00
10	REAR BUMPER CLIP @\$3.00	NECESSARY	30.00	30.00
1	REAR BUMPER RETAINER RH	BROKEN	30.00	30.00
1	REAR BUMPER RETAINER LH	NOT NECESSARY	30.00	-
	LESS 20% DISCOUNT		-	-110.40
			970.00	441.60
<b>SPECIAL NETT ITEMS</b>				
2	REVERSE SENSOR @\$200.00 (SN)	NOT NECESSARY	400.00	-
			400.00	-
<b>LABOUR</b>				
	SPRAY PAINTING REAR BUMPER .		300.00	200.00
	REMOVE,REFIT AND REPAIR ACCIDENT AFFECTED PARTS.		300.00	200.00
	REMOVE AND REFIT REAR BUMPER REVERSE SENSOR .		160.00	30.00
	CHECK AND RECTIFY ELECTRICAL WIRING.		30.00	30.00
			790.00	460.00
<b>GRAND TOTAL</b>			<b>2,160.00</b>	<b>901.60</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>700.00</b>

Report Ref No. CC6/CT121011825/Ega3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



# LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SMF 3738A

## INSPECTION






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R











# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SMF 3738A

## RE-INSPECTION

