

Grey
 BIFROST AUTO PTE LTD
 8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875
 Tel: +65 64524457
 Fax: +65 64524584
 Company Reg No: 201929175W

Estimate

Vehicle No: SKN1609J
 Model and make: Honda fit Shuttle
 Chassis: GG73104763

Qty	Spare parts	List price	2014
1	Tailgate	\$	✓ 890.20 DDV
1	Tailgate centre emblem	\$	53.00 -65.50 } NECV
1	Tailgate "FIT SHUTTLE" emblem	\$	55.00 66.10 } NECV
1	Tailgate windscreen glass rubber seal	\$	✓ 164.30 } NECV
1	Tailgate chrome moulding	\$	110.35 -321.20 } NECV
1	Tailgate reverse camera	\$	608.20 NDX
1	Tailgate wiper motor	\$	589.70 } NDX
1	Tailgate wiper arm	\$	81.20 } NDX
1	Tailgate lock	\$	113.50 } NDX
1	Tailgate lock catch	\$	24.70 } NDX
1	Tailgate inner trim board	\$	145.20 BRV
1	Tailgate weatherstrip	\$	101.40 TNV
1	Rear bumper	\$	510.00 780.20 DDV
1	Rear bumper RH reflector	\$	78.30 } NDX
1	Rear bumper LH reflector	\$	78.30 } NDX
1	Rear bumper RH side retainer	\$	28.60 64.70 } NECV
1	Rear bumper LH side retainer	\$	28.60 64.70 } NECV
1	Rear bumper RH inner sponge	\$	92.30 } NSX
1	Rear bumper LH inner sponge	\$	92.30 } NSX
1	RH taillamp assy	\$	435.20 680.40 BRV
1	RH taillamp sponge gasket	\$	✓ 21.20 NECV
1	LH taillamp assy	\$	680.40 } NSX
1	LH taillamp sponge gasket	\$	21.20 } NSX
1	End panel	\$	✓ 455.60 DDV
1	End panel inner garnish	\$	✓ 95.80 BRV
1	Rear RH fender inner trim board	\$	394.10 490.50 BRV
1	Rear LH fender	\$	712.40 980.40 DDV
1	Rear LH fender inner trim board	\$	394.10 490.50 BRV
1	Rear compartment panel top board	\$	589.20 NDX

\$ 4795.05 8,927.20
 -20% \$ 959.01 1,785.44
 \$ 3836.04 7,141.76

Qty Spare parts

Special Nett

1	Tailgate windscreen glass sealant	\$	30.00 70.00 NECV
1	Tailgate windscreen glass inner seal	\$	20.00 50.00 NECV
1	Tailgate "One" sticker	\$	✓ 30.00 } NECV
1	Tailgate "Garage & Colour" sticker	\$	30.00 55.00 } NECV

1 set Tailgate inner trim board clips
 1 set Rear bumper clips
 1 set Rear bumper reverse sensor
 1 set End panel inner garnish clips
 1 End panel joint sealant
 1 set Rear RH fender inner trim board clips
 1 set Rear LH fender inner trim board clips
 1 Rear LH fender joint sealant
 1 Rear LH fender glass sealant
 1 Rear LH fender glass inner seal
 1 Rear number plate

\$	30.00	60.00	NECV
\$	30.00	70.00	NECV
\$	200.00	280.00	SCV
\$	20.00	40.00	NECV
\$	30.00	60.00	NECV
\$	20.00	60.00	} NECV
\$	20.00	60.00	
\$		60.00	} NNX
\$		70.00	
\$		40.00	} NDX
\$		80.00	
	<u>460.00</u>		

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
 To panel beating, cut / weld and re-align all affected panels

\$ 800.00 1,400.00 ✓

Spray painting on affected panels

\$ 800.00 1,200.00 ✓

Check wiring and lighting system

\$ 100.00 NNX

Apply rust coating chemical on affected panels

\$ 100.00 NNX

Remove and reinstall tailgate windscreen glass to assist repair

\$ 120.00 220.00 ✓

Remove and replace tailgate inner components to assist repair

\$ 80.00 120.00 ✓

Remove, replace and adjust tailgate reverse camera to assist repair

\$ 100.00 NNX

Remove and replace rear inner trim, garnish, roof lining, seats and carpet to assist repair

\$ 80.00 250.00 ✓

Remove and replace rear bumper reverse sensors to assist repair

\$ 60.00 100.00 ✓

Remove and reinstall rear LH fender glass to assist repair

\$ 120.00 NNX

Remove and replace rear bumper reverse sensors to assist repair

\$ 60.00 70.00 ✓

Final amount \$ 2,600.00 12,006.76

Survey & Resurvey

22/11/2021

1208 hrs.

TGum Min

Lump Sum repair
 Repair days 6

Parts 3836.04

SN 40.00

Labour 2000.00

6296.04

@20% 1259.21

5036.83

~~LS 5050.83~~

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TGum Min

17/4/2022