



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2204598

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 26/07/2022
Reference CC3/CTI21011850/Rpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMB 1359U
Insured Veh. SGU 8495J
Claim No. SNM21D206741/C02
Policy No. DMHCSNA00002172100
Accident Date 12/11/2021
Inspection Date 19/11/2021

Description	Total
Survey Inspection	280.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	280.00
GST (7%)	19.60
Grand Total	299.60

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI21011850/Rpa3q2 Date: 26/07/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SGU 8495J	Veh. Inspected	SMB 1359U
	Policy No.	DMHCSNA00002172100	Coverage (\$)	0.00
	Claim No.	SNM21D206741/C02	Excess (\$)	0.00
	Assign From		Assign Date	19/11/2021
2. Vehicle Particulars & Condition				
	Make & Model	MAN NL320F (A22)	c.c	10518
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WMAA22ZZ7D7001805	Colour	MULTI COLOUR
	Odometer	607834 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	275/70 R22.5	FIRENZA	8 mm
	L/H Front Tyre	275/70 R22.5	FIRENZA	8 mm
	R/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	8/8 mm
	L/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	8/8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	12/11/2021	Inspection Date	19/11/2021
	Survey held at	STRIDES AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 1359U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER REAR CENTRE MAN A22 'C' SERIES	CRACKED	1,625.00	1,625.00
1	FRAME REAR BUMPER FOR MAN A22 BUS	BENT	1,423.20	1,423.20
1	BRACKET ATTACHMENT FOR MAN A22 BUS	BENT	569.30	569.30
1	DOOR ENGINE REAR MAN A22 'C' SERIES	TO REPAIR SEE LABOUR	1,625.00	-
2	DRAIN VALVE @\$194.47	BENT	388.94	388.94
	LESS 10% DISCOUNT		-	-400.64
			5,631.44	3,605.80
	<u>SPECIAL NETT ITEMS</u>			
1	STICKER SMRT (SN)	NECESSARY	75.00	75.00
1	STICKER 60KM/H (SN)	NECESSARY	5.00	5.00
			80.00	80.00
	<u>LABOUR</u>			
	TO REMOVE & INSTALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS .INCLUSIVE OF THE REPAIR OF DOOR ENGINE REAR MAN A22 'C' SERIES.		1,000.00	795.00
	SPRAY PAINTING & PANEL BEATING.		616.00	528.00
	TOWING CHARGE.		200.00	200.00
			1,816.00	1,523.00
	GRAND TOTAL		7,527.44	5,208.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,450.00

Report Ref No. CC3/CTI21011850/Rpa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMB 1359U

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMB 1359U

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

