

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 60067**
Date Estimated : **19/11/2021**
Prepared By : **Foong Shiuh Jye**

- ESTIMATE REPAIR FOR -

Ong Wei-Wei
20 Pine Grove
#01-01 Cavendish Park

Singapore 597595

- ACCOUNT -

303

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFE23L	WBA3B16060NP55139	05/06/2013	320iA4	65837

DESCRIPTION	ORIGINAL PRICE	NETT
* To replace rear bumper and attachments, rear bumper carrier, rear silencer heat shield including knock out dented area caused by the accident .	1,275.00	1,275.00
To respray rear bumper.	986.00	986.00
To remove old PDC assembly and reconnect to new bumper including conduct check for proper function.	168.00	168.00
To check electrical wiring system and lighting at the rear section for proper function.	168.00	168.00
Sundries.	80.00	80.00

DESCRIPTION	UNIT PRICE	QTY	NETT
RR BUMPER BOTTOM REINFORCEMENT	62.60	1.00	62.60
REAR BUMPER CARRIER (ECE)	470.25	1.00	470.25
DECORATIVE STRIP (LUXURY LINE)	82.85	1.00	82.85
REAR BUMPER PANEL PRIMED (LINES)	1,184.75	1.00	1,184.75
REAR PDC HOLDER SET	25.75	1.00	25.75
REAR SILENCER HEAT SHIELD	73.60	1.00	73.60
(DG/SL) ADHESIVE SET K6	53.05	1.00	53.05

SUPPLEMENTARY ITEMS

Total Labour :	2,677.00
Total Parts :	1,952.85
Total Labour & Parts :	4,629.85
Deduction for Excess :	0.00
Total Repair Costs less Excess:	4,629.85
GST @7%:	324.09
Grand Total :	4,953.94